

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 24 Nov 2022

## **Preliminary Advice**

Insured Vehicle No	: SKF1637U		
TP Vehicle No	: SMM1743K	Accident Date	: 19/07/2022
Make	: HONDA GRACE HYBRID	Assignment Date	: 29/09/2022
Date of Inspection	: 22/07/2022	Est. Duration of Repair	: 12
Inspection At	: MY CAR CREDIT PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,789.08
Revised Amount	:S\$	11,157.28
Check Items (Estimated)	:S\$	
Total	:S\$	11,157.28
Lump Sum Repair	:S\$	8,900.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a "Without Prejudice" basis.  
Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.