



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

TO: AIG INSURANCE
AIG Building
78 Shenton Way, Level 1
Singapore 079120

C/O: LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

LETTER OF DEMAND

Tax Invoice : 202209-0151
Date : 28/09/2022
Vehicle : SKG1527Z
Make Model : BMW LED NAV HUD MSPT, 1998cc
Accident Date : 12/07/2022 10:16 (SGT)
Accident Location: 1 KAKI BUKIT AVENUE 6

<u>Particular</u>	<u>Amount</u>
1. COST OF REPAIR	\$4,874.81
2. LOSS OF USE FOR 01 Days x @\$250.00 per day	\$ 250.00
3. Pre-Repair Inspection for 2 days x @\$250.00 per day	\$ 500.00
4. GIA/LTA SEARCH FEE	\$. 7.45

Singapore Dollars: Four Thousand Two Hundred Twenty-Seven & Cents Forty-Five Only



YSK Auto Workshop

Total S\$: 5,632.26
=====