



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

TO: AIG INSURANCE
AIG Building
78 Shenton Way, Level 1
Singapore 079120

C/O: LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

REPAIR BILL


Tax Invoice : 202209-0151
Date : 28/09/2022
Vehicle : SKG1527Z
Make Model : BMW LED NAV HUD MSPT, 1998cc
Accident Date : 12/07/2022 10:16 (SGT)
Accident Location: 1 KAKI BUKIT AVENUE 6

Particular	Amount
COST OF REPAIR	\$4,874.81

Total S\$: 4,874.81

=====

SAY TOTAL SINGAPORE DOLLARS: FOUR THOUSAND EIGHT HUNDRED SEVENTY-FOUR AND CENTS EIGHTY-ONE ONLY.



YSK Auto Workshop

