



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM22007032/Upa3q2 Date: 13/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 6585P	Veh. Inspected	FZ 7423J
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M0475Q	Excess (\$)	0.00
	Assign From		Assign Date	25/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c	399
	Engine No.	HIDDEN	Year of Reg.	2005
	Chassis No.	NC391102411	Colour	RED/WHITE
	Odometer	182784 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/60Z R17	BRIDGESTONE	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60Z R17	BRIDGESTONE	7 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/07/2022	Inspection Date	25/07/2022
	Survey held at	AHM PERFORMANCE BLK 1 KAKI BUKIT AVE 6 #02-46 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	