

FZ 7H23J

V-TRC3

23/7/22

Rear tail cover

@670

cnc — 485

taillamp

@440

cnc — 295

Rear number plate

@24

sca 20

Rear wheel mudguard

@280

cnc —

(10%)

Spray paintwork

@250

180

Tow charge

@50

11X

labour charge

@280

200

Not Allowed

her

2/5 \$1050

3 days.

Tel. ph. After 4pm

25/7/22

2-1080  
 102  
 972  
 380  
 1352  
 202  
 1081

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: