



WEARNES AUTOMOTIVE PTE LTD

45 LENG KEE ROAD SINGAPORE 159103

Tel: +65 64304930 Fax: +65 6474 0853 www.ducatisingapore.com

Repair Estimate

Date	26 Sep 2022
Bike Number	FBK4323K
Chassis No.	ZDMK100AAFB003370
Customer	Mr Brillet Eric Nicolas
Address	
Email	

Model	SCR FT
Mileage	
Contact	
Svc. No.	
Youtech	
Technician	

No.	Labour Code	Description	Qty	Unit Price	Amount
		Sub-Total			

No.	Part Number	Description	Qty	Unit Price	Amount
1		COMPLETE SPRING NEC	3	\$25.10	\$75.30
2		THRUST WASHER NEC	2	\$1.00	\$2.00
3		THRUST WASHER NEC	2	\$1.70	\$3.40
4		CHAIN LINK NEC	1	\$15.80	\$15.80
		Sub-Total			\$96.50

1. This estimate is compiled with visual inspection on the above mentioned motorcycle.
2. During the repair process, additional parts and labour may be required to complete the repairs works. A supplementary estimate shall be created accordingly.
3. The undersigned signature represents the acceptance of this estimate and the permission to proceed with repair works.

Signature: _____

Total Labour:	\$0.00
Total Parts:	\$96.50
GST:	\$6.76
Grand Total:	\$103.26