



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : M12D18982208

Date: 12<sup>th</sup> Aug 2022

Our Ref : CS/UOI22007036/Ecy3e2

**M/s United Overseas Insurance Ltd**

146 Robinson Road  
#02-01 Uoi Building  
Singapore 068909  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMV 1553U  
ACCIDENT ON 17/07/2022**

Instruction was received to inspect the vehicle Reg. No. SMV 1553U. The inspection was conducted on 27/07/2022 at the premises of M/s Performance Motors Ltd, 303 Alexandra Road, Singapore 159941.

The following vehicle information was recorded:

Registration Number	: SMV 1553U
Make/Model	: B.M.W. 216I Gran Tourer
Year of Registration	: 2020
Body Colour	: Black
Chassis Number	: WBA6V120305R41568
Engine Capacity	: 1499 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$128,076.20 (Sin Dollars: One Hundred Twenty-Eight Thousand Seventy-Six and Twenty cents only.) (Include check items S\$60,336.90Nett) (Details see photographs enclosed)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**Total Loss**".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 147,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 58,982.00)

S\$ 88,018.00

Less: Excess

(S\$ 1,500.00 )

Nett Liability

S\$ 86,518.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 128,076.20

(Include check items S\$60,336.90Nett)

Less:Excess

(S\$ 1,500.00)

Nett Liability

S\$ 126,576.20

(a) – (b) =

(S\$ 40,058.20 )

=====

The amount of estimated saving of S\$40,058.20 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

CHEN TSUE YEE  
Automotive Assessor

K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MII(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIAd, AM,NJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.