

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En A	Autom	obile	
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	R	ef:	CS/CTI22007068/Ucy3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	D	ate:	25/07/2022	
			C	ode:	CTI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GY 6930L	Veh. Inspected		SMD 5652K	
	Policy No.	DMCVSNW00003292203	Coverage (\$)		0.00	
	Claim No.	SNM22D205145/C02/GY6930L/ CHNGPW	Excess (\$)		0.00	
	Assign From	ADELINE CHNG	Assign Date		25/07/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN Year of Reg.				
	Chassis No.	Colour Steering				
	Odometer					
	Brakes	Modification				
	General					
3.		Conditions of Tyres				
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	25/07/2022	Inspection Date		26/07/2022	
	Survey held at	urvey held at FALCON-AIR AUTO SERVICES PTE LTD				
		BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840				
5a.	Sa. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					