# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

#04-01 Suntec Tower Three Paya Ubi Industrial Park Singapore 038988 Singapore 408933

Attn: Date: 26 Jul 2022

## **Preliminary Advice**

Vehicle No: SLG543XAccident Date: 25/07/2022Make: HONDA CIVICPolicy No.: DMPG21011572

Assignment Date : 26/07/2022 Excess : \$\\$0.00 Date of Inspection : 26/07/2022 Est. Duration of Repair : 05

Inspection At : PRECISE AUTO SERVICE

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,357.75
Revised Amount	:S\$	3,641.25
Check Items (Estimated)	:S\$	1,056.00
Total	:S\$	4.697.25

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 58,000.00 COE / PARF Rebate :S\$ 35,333.00

Salvage Value :S\$

Margin for Repair :S\$ 22,667.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.