>











LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIANZ INSURAN	ICE SINGAPORE PTE LTD		Ref:	CS3/AIS22007120/Tcy3	
	79 ROBINSON ROAD #09-01 SINGAPORE 068897			Date:	26/07/2022	
	#09-01 SINGAPOR	E 008897		Code:	AIS	
1.		Policy Particulars :-	. (THIRD PARTY			
	Insured Veh.	SDQ 56C	Veh. Inspected	-	SMN 5553K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 22005793SL	Excess (\$)		0.00	
	Assign From	SHANTI	Assign Date		26/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No. Colour					
	Odometer	-	Steering			
	Brakes	akes Modification				
	General					
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
_						
5.	General Information					
	Accident Date	24/07/2022	Inspection Dat	е	27/07/2022	
	Survey held at	APEX MOTORING				
		25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800.				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					