

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

26 JULY 2022

China Taiping Co (S) Pte Ltd
105 Cecil Street
#18-00 The Octagon
Singapore 069534

*Not Notation
L1 Rty @ 1150h
Running After Repair
3 days*

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SLM5230J
Accident involving vehicle no: SMM7283G/SLM5230J
DOA: 23/07/2022 at PRINSEP STREET

Dear officer in charge
Estimate cost of repair for vehicle no: SMM7283G
To supplied:

Description	Qty	Amount
Rear bumper	1	482.00
Rear bumper retainer	2	185.00
Rear bumper reflector	2	113.80
Rear bumper sponge	1	117.50
Tailgate	1	754.30
Tailgate reflector	2	233.20
Tailgate - corolla emblem	1	45.00
Tailgate - altis emblem	1	42.30
Tailgate - 1.6 emblem	1	32.10
Tailgate - VVT-I emblem	1	38.40
End panel	1	581.20
Parts		2,624.80
Parts less 25%		1,968.60

1. Reverse sensor
2. Lalamove body sticker
3. Remove damaged parts & attachments
Cut/weld damaged panel
Repair dented area
Replace/realign all parts into same position
4. To spray paint

*67 220.00 2000h
80.00 400h*

500.00 300L

400.00

3168.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: