



EQBH PLE LTD®

REGISTRATION NO:201709306E

25 Kaki Bukit Road 4
Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391
Email: equator.brotherhood@gmail.com


PRE - REPAIR INSPECTION

Bike Model: Yamaha X1R

Bike Plate: FBB8293J

S/N	Parts Description	Quantity	Unit Price	Amount
1	Yamaha fairing (colored)	1	\$ 400.00	\$ cut 400.00
2	Yamaha fairing (matte black)	1	\$ 140.00	\$ cut 140.00
3	Yamaha front suspension (left)	1	\$ 395.00	\$ X 395.00
4	Yamaha front suspension (right)	1	\$ 395.00	\$ X 395.00
5	Yamaha triple clamp (bottom)	1	\$ 250.00	\$ X 250.00
6	Yamaha steering cone	1	\$ 95.00	\$ X 95.00
7	Yamaha handlebar	1	\$ 95.00	\$ X 95.00
8	Yamaha handlebar bracket	1	\$ 65.00	\$ X 65.00
9	Yamaha headlight	1	\$ 220.00	\$ cut 220.00
10	Yamaha front signal (left)	1	\$ 45.00	\$ X 45.00
11	Yamaha front signal (right)	1	\$ 45.00	\$ cut 45.00
12	Yamaha front rim	1	\$ 220.00	\$ cut 220.00
13	Yamaha front wheel bearings	2	\$ 35.00	\$ cut 70.00
14	Yamaha front wheel seal	2	\$ 15.00	\$ cut 30.00
15	Yamaha front wheel shaft	1	\$ 50.00	\$ cut 50.00
16	Yamaha front brake disc	1	\$ 130.00	\$ X 130.00
17	Yamaha front brake caliper	1	\$ 220.00	\$ X 220.00
18	Yamaha front brake lever	1	\$ 45.00	\$ X 45.00
19	Yamaha front brake master cylinder	1	\$ 150.00	\$ X 150.00
20	Yamaha front brake master cylinder bracket	1	\$ 25.00	\$ X 25.00
21	Yamaha front brake hose	1	\$ 95.00	\$ X 95.00
22	Yamaha front tire valve	1	\$ 15.00	\$ X 15.00
23	Yamaha clutch lever	1	\$ 45.00	\$ X 45.00
24	Yamaha clutch cable	1	\$ 45.00	\$ X 45.00
25	Yamaha clutch lever holder	1	\$ 45.00	\$ X 45.00

1250
120
180
-200
30
X
M



EQBH PLE LTD®

REGISTRATION NO: 201709306E

25 Kaki Bukit Road 4

Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391

Email: equator.brotherhood@gmail.com

PRE - REPAIR INSPECTION

Bike Model: Yamaha X1R

Bike Plate: FBB8293J

S/N	Parts Description	Quantity	Unit Price	Amount
26	Yamaha clutch lever holder screw	1	\$ 10.00	\$ X 10.00
27	Yamaha clutch cable length adjuster	1	\$ 20.00	\$ X 20.00
28	Yamaha foot step bar	1	\$ 65.00	\$ X 65.00
29	Yamaha rider footrest (left)	1	\$ 25.00	\$ X 25.00
30	Yamaha pillion foot rest bracket (left)	1	\$ 65.00	\$ X 65.00
31	Yamaha pillion foot rest (left)	1	\$ 25.00	\$ X 25.00
32	Yamaha gear shifter	1	\$ 65.00	\$ X 65.00
33	Yamaha mirror set	2	\$ 35.00	\$ X 70.00
34	Yamaha front opened basket	1	\$ 60.00	\$ X 60.00
35	Yamaha handle grip	1	\$ 35.00	\$ X 35.00
36	Number plate front	1	\$ 15.00	\$ X 15.00
37	IU bracket	1	\$ 85.00	\$ X 85.00
38	CNC bar end balancer	1	\$ 120.00	\$ X 120.00
39	LiquiMoly front brake fluid	1	\$ 20.00	\$ X 20.00
40	Towing 1-trip (Workshop to reporting center)	1	\$ 65.00	\$ 40 65.00
41	Towing 1-trip (Reporting center to workshop)	1	\$ 65.00	\$ X 65.00
42	Towing 1-trip (TP compound to workshop)	1	\$ 65.00	\$ 40 65.00
43	Chassis alignment	1	\$ 480.00	\$ X 480.00
44	Labor	1	\$ 480.00	\$ 200 480.00
45		940		\$ -
46		107,846		\$ -
47		280		\$ -
48		1126		\$ -
49		154900		\$ -
50		03 days		\$ -
51				\$ -

LKH Auto Consultants hence notify

the Repairer of the following:

49 resurvey before/after spray painting

50 To display damaged part(s) during resurvey

51 Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EQBH PLE LTD®

REGISTRATION NO: 201709306E

Tanfiah 97495749
28/7/22 C530pm
L/S Resurvey after repair
Tanfiah 0164200000
03 days