



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBB 8293J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	YAMAHA FAIRING (COLORED) (CONSISTENT)	CUT	400.00	250.00
1	YAMAHA FAIRING (MATTE BLACK) (CONSISTENT)	CUT	140.00	120.00
1	YAMAHA FRONT SUSPENSION (LEFT) (CONSISTENT)	NOT NECESSARY	395.00	-
1	YAMAHA FRONT SUSPENSION (RIGHT) (CONSISTENT)	NOT NECESSARY	395.00	-
1	YAMAHA TRIPLE CLAMP (BOTTOM) (CONSISTENT)	NOT NECESSARY	250.00	-
1	YAMAHA STEERING CONE (CONSISTENT)	NOT NECESSARY	95.00	-
1	YAMAHA HANDLEBAR (CONSISTENT)	NOT NECESSARY	95.00	-
1	YAMAHA HANDLEBAR BRACKET (CONSISTENT)	NOT NECESSARY	65.00	-
1	YAMAHA HEADLIGHT (CONSISTENT)	CUT	220.00	180.00
1	YAMAHA FRONT SIGNAL (LEFT) (CONSISTENT)	NOT NECESSARY	45.00	-
1	YAMAHA FRONT SIGNAL (RIGHT) (CONSISTENT)	CUT	45.00	45.00
1	YAMAHA FRONT RIM (CONSISTENT)	BENT	220.00	200.00
2	YAMAHA FRONT WHEEL BEARINGS @\$35.00 (CONSISTENT)	NECESSARY	70.00	70.00
2	YAMAHA FRONT WHEEL SEAL @\$15.00 (CONSISTENT)	NECESSARY	30.00	30.00
1	YAMAHA FRONT WHEEL SHAFT (CONSISTENT)	BENT	50.00	30.00
1	YAMAHA FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	130.00	-
1	YAMAHA FRONT BRAKE CALIPER (CONSISTENT)	NOT NECESSARY	220.00	-
1	YAMAHA FRONT BRAKE LEVER (CONSISTENT)	NOT NECESSARY	45.00	-
1	YAMAHA FRONT BRAKE MASTER CYLINDER (CONSISTENT)	NOT NECESSARY	150.00	-
1	YAMAHA FRONT BRAKE MASTER CYLINDER BRACKET (CONSISTENT)	NOT NECESSARY	25.00	-
1	YAMAHA FRONT BRAKE HOSE (CONSISTENT)	NOT NECESSARY	95.00	-
1	YAMAHA FRONT TIRE VALVE (CONSISTENT)	NOT NECESSARY	15.00	-
1	YAMAHA CLUTCH LEVER (CONSISTENT)	NOT NECESSARY	45.00	-
1	YAMAHA CLUTCH CABLE (CONSISTENT)	NOT NECESSARY	45.00	-
1	YAMAHA CLUTCH LEVER HOLDER (CONSISTENT)	NOT NECESSARY	45.00	-
1	YAMAHA CLUTCH LEVER HOLDER SCREW (CONSISTENT)	NOT NECESSARY	10.00	-
1	YAMAHA CLUTCH CABLE LENGTH ADJUSTER (CONSISTENT)	NOT NECESSARY	20.00	-
1	YAMAHA FOOT STEP BAR (CONSISTENT)	NOT NECESSARY	65.00	-

Report Ref No. CS/ASM22007166/Tcy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	YAMAHA RIDER FOOTREST (LEFT) (CONSISTENT)	NOT NECESSARY	25.00	-
1	YAMAHA PILLION FOOT REST BRACKET (LEFT) (CONSISTENT)	NOT NECESSARY	65.00	-
1	YAMAHA PILLION FOOT REST (LEFT) (CONSISTENT)	NOT NECESSARY	25.00	-
1	YAMAHA GEAR SHIFTER (CONSISTENT)	NOT NECESSARY	65.00	-
2	SET YAMAHA MIRROR @\$35.00 (CONSISTENT)	NOT NECESSARY	70.00	-
1	YAMAHA FRONT OPENED BASKET (CONSISTENT)	NOT NECESSARY	60.00	-
1	YAMAHA HANDLE GRIP (CONSISTENT)	NOT NECESSARY	35.00	-
1	NUMBER PLATE FRONT (CONSISTENT)	CUT	15.00	15.00
1	IU BRACKET (CONSISTENT)	NOT NECESSARY	85.00	-
1	CNC BAR END BALANCER (CONSISTENT)	NOT NECESSARY	120.00	-
1	LIQUIMOLY FRONT BRAKE FLUID (CONSISTENT)	NOT NECESSARY	20.00	-
	LESS 10% DISCOUNT		-	-94.00
			4,010.00	846.00
	LABOUR			
	TOWING 1-TRIP (WORKSHOP TO REPORTING CENTER).		65.00	40.00
	TOWING 1-TRIP (REPORTING CENTER TO WORKSHOP).	NOT NECESSARY	65.00	-
	TOWING 1-TRIP (TP COMPOUND TO WORKSHOP).		65.00	40.00
	CHASSIS ALIGNMENT.	NOT NECESSARY	480.00	-
	LABOR.		480.00	200.00
			1,155.00	280.00
GRAND TOTAL			5,165.00	1,126.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/ASM22007166/Tcy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.