



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22007173/Evy3m4 Date: 08/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4535L	Veh. Inspected	FBR 8549M	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/06/22/2001	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	27/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA NMAX	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MH3SG5680LK038362	Colour	BLACK	
Odometer	89467 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R14	PIRELLI	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/70 R14	PIRELLI	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2022	Inspection Date	01/08/2022	
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	