

QUOTE

SML9512M Honda Vezel

Date
02 Aug 2022

Expiry

Account Number

Quote Number
QU-0018

Reference

Genus Performance
39 Woodlands Close
#03-03
Mega@Woodlands
Singapore 737856
Tel: 6957 7077 / 8188
8399
UEN: 53386717K

Description	Quantity	Unit Price	Tax	Amount SGD
Front bonet ✓ DD	1.00	892.30	Tax Exempt	892.30 ✓
Front bumper ✓ CRU	1.00	745.60	Tax Exempt	745.60 ✓
Front grill ✓ BR	1.00	360.00	Tax Exempt	360.00 ✓
Front grill chrom ✓ BR	1.00	230.00	Tax Exempt	230.00 ✓
Logo ✓ NEC	1.00	80.00	Tax Exempt	80.00 35 (Net)
Radiator garnish (Bonnet lock bracket) BR	1.00	95.00	Tax Exempt	95.00 76 ✓
Radiator ganish bracket NN	1.00	85.00	Tax Exempt	85.00 ✗
Number plate ✓ CUT	1.00	80.00	Tax Exempt	80.00 30 (Net)
Number plate holder ✓ CUT	1.00	50.00	Tax Exempt	50.00 25 (Net)
Head lamp lower bracket ✓ BR	<u>2.00</u>	80.00	Tax Exempt	160.00 ✓
Reinforcement BT	1.00	420.00	Tax Exempt	420.00 321 ✓
Outside temperature sensor ✓ BR	1.00	180.00	Tax Exempt	180.00 118 ✓
Headlamp(FL) NN	1.00	1,300.00	Tax Exempt	1,300.00 ✗
Fander(FL) (LH) Repair	1.00	230.00	Tax Exempt	230.00 ✗
Bumper retainer BR	<u>2.00</u>	80.00	Tax Exempt	160.00 ✓
Bonet lock NN	1.00	160.00	Tax Exempt	160.00 ✗
Spray	1.00	1,200.00	Tax Exempt	1,200.00 700 ✓
Panel beat	1.00	1,200.00	Tax Exempt	1,200.00 400 ✓
Computer reset (& sealant, bumper clip) NEC	1.00	350.00	Tax Exempt	350.00 80 ✓ (Net)
			Subtotal	7,490.00

Description	Quantity	Unit Price	Tax	Amount SGD
			Total Tax Exempt 0%	0.00
			TOTAL SGD	7,490.00

Part - 3062.90 Nett - 170 Labour & spray - 1
-20%
2450.32

total - 3720.32

Terms

Steve (LKK)
29/07/22
Without Prejudice
4 days
Lump-sum
Resurvey after spray

L/S - 2976.25
= 3000

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: