



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

INV No. AC2205373

ACCIDENT CLAIMS SECTION

INV Date 31/08/2022

(SPORE POLICE FORCE)

Reference CS3/SPF22007193/Ecy3e2

POLICE LOGISTICS BASE (PLB)

Code SPF

1 HEMMANT ROAD

SINGAPORE 438675

PROFESSIONAL SERVICE FEE

Vehicle No. GBC 3073E

Insured Veh. GBB 7823L

Claim No. ACS/105/009/2022/045

Policy No.

Accident Date 25/07/2022

Inspection Date 28/07/2022

Description	Total
Damage Assessment	180.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	180.00
GST (7%)	12.60
Grand Total	192.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM