

EST/QUOTE NO. SQ007506

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD #16-01
CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : . FAX NO: 65073849

DATE 27/07/2022
ACCIDENT DATE : 20/07/2022
VEHICLE NO : SJL3391U
CHASSIS/ENG.NO : MR053ZEE106122051
VEHICLE MODEL : TOYOTA ALTIS
CLAIM NO : D22002268MFSH/STRID
POLICY NO :
REMARK 3391 TP FIRST CAP
AGST SHB786K

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER <i>repair</i>	612.25	25	459.19	459.19 <i>P</i>
2	1	PC	REAR BUMPER RETAINER RH <i>X</i>	172.10	25	129.07	129.07 <i>X</i>
3	1	PC	REAR FENDER RH <i>bt ✓</i>	1,082.25	25	811.69	811.69 <i>✓</i>
4	1	PC	REAR DOOR RH <i>repair</i>	971.75	25	728.81	728.81 <i>P</i>
5	1	PC	RR DOOR OUTER CTR MOULDING RH <i>repair</i>	174.45	25	130.84	130.84 <i>P</i>

SUB-TOTAL: 2,259.60

\$811.69

** NETT PRICE **							
1	10	PC	REAR BUMPER CLIPS <i>X</i>	4.00	10	3.60	36.00
SUB-TOTAL							36.00 <i>X</i>

**** WORK LABOUR ****

TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS

TO SPRAY PAINTING ON AFFECTED AREAS

TO CHECK WIRING

TO TRANSFER DOOR GLASS MECHANISM LH

Anti Rust — \$100

800.00 *600* ~~800.00~~

1000.00 *600* ~~1,000.00~~

30.00 *X* 30.00

60.00 *X* 60.00

SUB-TOTAL 1,890.00

\$1200

JOYCE

PAGE: 1 of 1

SUB-TOTAL : S\$ 4,185.60

ADD 7% GST. S\$ 292.99

GRAND TOTAL : S\$ 4,478.59

*Total \$211.69
less 20% = \$1689.35
ok? pls RMA.
Shawn 17/10/2022*

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.