



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22004763/Eqy3e2-1	
			Date: 12/08/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4897S	Veh. Inspected	SMZ 5307S
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/22/2036	Excess (\$)	0.00
	Assign From	ANA MAGNAYE	Assign Date	28/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MR2B23F3001220828	Colour	BLACK
	Odometer	56025 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	DUNLOP	4 mm
	L/H Front Tyre	185/60 R15	DUNLOP	4 mm
	R/H Rear Tyre	185/60 R15	DUNLOP	4 mm
	L/H Rear Tyre	185/60 R15	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/05/2022	Inspection Date	20/05/2022
	Survey held at	CAR LABORATORIES PTE LTD NO. 1 BUKIT BATOK CRESCENT #04-56 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	