

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI22007230/Uvy3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	12/08/2022	
			C	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLU 3777U	Veh. Inspected		SLA 6519J	
	Policy No.	P10645080R00	Coverage (\$)		0.00	
	Claim No.	C10016606/CD	Excess (\$)		0.00	
	Assign From	SALIZAWATI	Assign Date		29/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH (A)	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	ZGE206028241	Colour		WHITE	
	Odometer	111895 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	PREMIO		6 mm	
	L/H Front Tyre	195/65 R15	PREMIO		6 mm	
	R/H Rear Tyre	195/65 R15	PREMIO		6 mm	
	L/H Rear Tyre	195/65 R15	PREMIO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/07/2022	Inspection Date		29/07/2022	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	15/11 / COOKBAIN	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: