

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

MVA : Loke Wai Yiang

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/07/2022
Vehicle Reg. No.:	SHC3416D	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	01/03/2019
Vehicle Colour:	BLUE	Chassis No:	KMHC851CVKU141436
Engine No:	G4LEJU191405		
Odometer:	502187 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,885.52
Miscellaneous Items	11.00
Labour	910.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,806.52
+ GST 7.00% (S\$)	196.46
Nett Amount (S\$)	3,002.98

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3416D/26/07/2022 16:04**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	459.40 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00	22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	394.80 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	138.10 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	138.10 FL
7	1		*REAR BUMPER LOWER CTR MOULDING	20.00	0.00	155.00 FL
8	1		*ANTENNA SMARTKEY	20.00	0.00	40.50 FL
9	1		*REAR BUMPER FOG LAMP	20.00	0.00	201.50 FL
10	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	180.00 F
11	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	55.00 F
12	1		*REAR BUMPER RUBBER MAT	0.00	0.00	50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,285.65
- List Item Discount on L Items (\$\$)	400.13
Total Parts (\$\$)	1,885.52

ComfortDelGro Engineering Pte Ltd/SHC3416D/26/07/2022 16:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 550.00
2	SPRAY PAINTING CHARGE	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (S\$)			910.00

ComfortDelGro Engineering Pte Ltd/SHC3416D/26/07/2022 16:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Temp No 97495749
 27/2/22 R fpu
 2 days
 1/3 Keenly after repair
 temp@lkhantol.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: