

Steve

AIG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 5891148264SGSum Insured: _____ Excess: 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 6617C Yr Regn: 30/11/20Type: N. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 c.o. 1984Colour: Blue A/C: Insured / Std / Nil / NASp. Reading: N/A T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAT772F53MA P11396Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rm / STD A/Rm orTyre Size: F: 245/40R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PirelliFront R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 7/7/22 D.O.I. 1/8/22Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-183KNew Car Price: 268K02/08/22 @ 4.04pm revert to AIG via Merimen.03/08/22 @ 1.49pm Kok Chong informed C/A via Merimen.03/08/22 @ 2.15pm Informed Tony C/A & ex: \$800 by email.

Date/Time, File Pass to?

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.A. (\$)

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0640/2022/EQ
DATE : 1-Aug-22
WIP : 34995

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. DINESH KUMAR S/O TEVERMUTHU
ADDRESS : BLK 455A ANG MO KIO STREET 44
#31-03
SINGAPORE 561455
TELEPHONE : HP +65 97364753
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070165966-01
VEHICLE NO : **SMW 6617 G**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI S-TRONIC
MODEL YEAR : 30/11/2020
ENGINE NO : DEM 027075
CHASSIS NO : WAUZZZF53MA011396
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Jul-22
PLACE OF ACCIDENT : 36 MIMOSA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	X
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ (photo) 800.00	?
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00	/
5	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	/
6	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ (photo) 3,600.00	/
SUB-TOTAL LABOUR CHARGES		: \$ 7,960.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	✓
8	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
9	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	✓
10	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	✓
11	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	250
12	TO PLACE VEHICLE ON CAR O-LINER. <i>Cphm</i>	S/N \$	2,400.00	7
SUB-TOTAL LABOUR CHARGES		:	\$ 6,280.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
14	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$ 280.00	?
15	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	?
16	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00	/
17	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS LHS SILL PANEL TRIM AND LHS FRONT DOOR. TO REPAIR RHS FRONT DOOR AND BOTH UPPER A-PILLARS. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT AND LHS A-PILLAR WITH LHS SILL PANEL. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 14,400.00 10 x 5000	5000
18	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT DOORS, BOTH UPPER A-PILLARS, LHS A-PILLAR, LHS SILL PANEL, DOOR ENTRANCE, LHS SILL PANEL TRIM AND LHS FRONT FENDER TOP SUPPORT.	\$ 11,000.00 6.5 x 550	3575
SUB-TOTAL LABOUR CHARGES		: \$ 28,160.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
19	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00 /	
20	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00 /	
TOTAL LABOUR CHARGES		: \$ 43,304.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$	2,493.00	
2	FRONT BUMPER SECURING STRIP / nec	2	\$	79.00	
3	FRONT BUMPER GRILLE - CENTER / BR	1	\$	219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE / BR	1	\$	293.00	
5	FRONT BUMPER SPOILER / MIS	1	\$	599.00	
6	FRONT BUMPER AIR GUIDE - LH / RH / MIS	21	\$	144.00	
7	FRONT BUMPER CLOSING ELEMENT / ?	1	\$	293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH / MIS	(2)	\$	302.00	
9	FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH / MIS	(2)	\$	108.00	
10	FRONT BUMPER TRIM - CENTER / MIS	1	\$	127.00	
11	RADIATOR GRILLE / BR	1	\$	1,881.00	
12	RADIATOR COVER CAP / ?	1	\$	141.00	
13	RADIATOR BRACKET / ?	1	\$	19.00	
14	RADIATOR SECURING PLATE / ?	1	\$	12.00	
15	FRONT PARKING AID SENSOR - INNER / OUTER / MIS	21	\$	530.00	
16	FRONT PARKING AID SENSOR ASSIST SYSTEM - SIDE / MIS	1	\$	265.00	
17	FRONT PARKING AID SEAL RING / APC	4	\$	10.00	
18	FRONT BUMPER WIRING SET / TA	1	\$	449.00	
19	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$	163.00	
20	FRONT BUMPER REINFORCEMENT BEAM / DN	1	\$	899.00	
SUB TOTAL SPARE PARTS		:	\$	9,026.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION - LH / RH / BR	21	\$ 82.00	
22	FRONT BUMPER BRACKET - LH / BT	1	\$ 254.00	
23	FRONT BUMPER TOP COVER / CRU	1	\$ 143.00	
24	CAUTION SIGN / M	1	\$ 16.00	
25	AIR CONDITIONER STICKER / ne	1	\$ 9.00	
26	FRONT LOCK CARRIER BRACKET / ?	1	\$ 154.00	
27	FRONT BUMPER SUPPORT - LH / RH / M	2	\$ 64.00	
28	POP RIVET / M	4	\$ 4.00	
29	FRONT HORN HIGH TONE - LH / BT BR	1	\$ 134.00	
30	FRONT HORN BRACKET - LH / BT	1	\$ 33.00	
31	FRONT FENDER - LH / RH / DO	21	\$ 2,378.00	
32	FRONT FENDER ATTACHMENT PARTS / M	1	\$ 55.00	
33	FRONT FENDER CLOSING ELEMENT - LH / M	1	\$ 83.00	
34	FRONT FENDER BRACKET - LH / BT	1	\$ 41.00	
35	POP RIVET / M	11	\$ 42.00	
36	FRONT FENDER BRACKET - LH / BT	1	\$ 65.00	
37	FRONT FENDER BRACKET - RH / BT	1	\$ 40.00	
38	FRONT FENDER BRACE - LH / BT	1	\$ 132.00	
39	FRONT FENDER BRACKET - LH / BT	1	\$ 55.00	
40	FRONT FENDER COVER - LH / BR	1	\$ 20.00	
SUB TOTAL SPARE PARTS		:	\$ 3,804.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00	
42	FRONT FENDER WHEEL HOUSING LINER - LH	1	\$ 299.00	
43	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 176.00	
44	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	
45	FRONT WHEEL SPOILER - LH / RH	2	\$ 164.00	
46	FRONT SPOILER - LH	1	\$ 39.00	
47	FRONT STONE CHIP GUARD - LH	1	\$ 57.00	
48	FRONT BRACKET TRIM - LH	1	\$ 27.00	
49	FRONT FENDER TRIM - LH / RH	2	\$ 342.00	
50	BONNET	1	\$ 3,491.00	
51	BONNET ATTACHMENT PARTS	1	\$ 128.00	
52	FRONT LID HINGE - LH / RH	2	\$ 932.00	
53	FRONT IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	
54	BONNET SOUND ABSORBER	1	\$ 382.00	
55	FRONT FENDER COVER - LH	1	\$ 81.00	
56	FRONT FENDER COVER	1	\$ 40.00	
57	FRONT HEADLAMPS COVER - LH	1	\$ 49.00	
58	FRONT FENDER COVER - LH	1	\$ 18.00	
59	BONNET ABSORBER	2	\$ 256.00	
60	BONNET STRIKER - LH	1	\$ 56.00	
SUB TOTAL SPARE PARTS		:	\$ 6,966.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	BONNET LOCK / BT	1	\$	228.00	
62	BONNET LOCK CABLE - RH ?	1	\$	82.00	
63	FRONT PLENUM CHAMBER COVER - RH / CVT	1	\$	108.00	
64	FRONT HEADLIGHT - LH / BR	1	\$	8,172.00	
65	HOSE / TN	1	\$	42.00	
66	FRONT COMPENSATING PIECE / MIS	3	\$	136.00	
67	FRONT LIFT CYLINDER BRACKET - LH / MIS	1	\$	17.00	
68	FRONT LIFT CYLINDER - LH / MIS	1	\$	217.00	
69	FRONT CORRUGATED PIPE / TN	1	\$	107.00	
70	COOLANT RADIATOR LOCK CARRIER MOUNTING / 00	1	\$	1,127.00	
71	FRONT COOLANT REGULATOR SUPPORT - LH ?	1	\$	43.00	
72	FLUID RESERVOIR AC CONDENSER ?	1		TBC	
73	A/C REFRIGERANT LINE ?	3	\$	844.00	
74	A/C REFRIGERANT PIPE / BT	1	\$	585.00	
75	FRONT A/C REFRIGERANT PIPE BRACKET / BR	2	\$	30.00	
76	CHARGE AIR COOLER / BT	1	\$	654.00	
77	PRESSURE PIPE ?	1	\$	496.00	
78	RADIATOR ?	1	\$	1,010.00	
79	FRONT READY-MIX COOLANT ? / PC	6	\$	282.00	
80	FRONT AIR GUIDE - LH / RH / UPPER / LOWER / BR 1.5	1	\$	118.00	
SUB TOTAL SPARE PARTS			\$	14,298.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	FRONT WINDSCREEN / <i>PR</i>	1	\$	1,625.00	
82	FRONT RAIN SENSOR GEL FOIL / <i>MC</i>	1	\$	130.00	
83	FRONT RETAINING SPRING X	1	\$	24.00	
84	FRONT CAMERA SILICONE PAD / <i>MC</i>	1	\$	123.00	
85	FRONT CAMERA PRIMER / <i>MC</i>	1	\$	22.00	
86	FRONT WATER DEFLECTOR STRIP - LH / RH X	2	\$	150.00	
87	FRONT DOOR - LH / <i>MC</i>	1	\$	3,977.00	
88	FRONT OUTER DOOR SEAL - LH / <i>MC</i>	1	\$	247.00	
89	BONDING AGENT / <i>MC</i>	1	\$	51.00	
90	CLEANING SOLUTION / <i>MC</i>	1	\$	74.00	
91	APPLICATOR / <i>MC</i>	1	\$	8.00	
92	FRONT DOOR CATCH - LH ?	1	\$	134.00	
93	FRONT DOOR TRIM - LH / RH / <i>PR</i>	12	\$	342.00	
94	FRONT TRIM STRIP WINDOW SLOT SEAL - LH / RH ?	12	\$	892.00	
95	ROOF MOLDING - LH / RH / <i>TA</i>	12	\$	1,412.00	
96	FRONT PILLAR A/B FRAME MEMBER - LH ?	1	\$	2,344.00	
97	FRONT SILL TRIM STRIP - LH / <i>PR</i> ?	1	\$	133.00	
98	FRONT SIDE MEMBER TRIM - LH / <i>CR4</i>	1	\$	916.00	
99	SECURING CLIPS ATTACHMENT PARTS / <i>MC</i>	1	\$	136.00	
100	ADHESIVE TAPES / <i>MC</i>	1	\$	221.00	
SUB TOTAL SPARE PARTS		:	\$	12,961.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
101	PICTOGRAM FOR AIRBAG / CHILD'S SEAT STICKER ¹	1	\$	27.00	
102	FRONT STEERING WHEEL AIRBAG ✓ ^{OR}	1	\$	4,092.00	
103	FRONT PASSENGER SIDE AIRBAG UNIT ✓ ^{OR}	1	\$	4,853.00	
104	FRONT HEAD AIRBAG UNIT - LH / RH ✓ ^{OR} ⁽²⁾	2	\$	4,138.00	
105	FRONT SPORTS STRNG WHEEL MULTIFUNCT ² ✓ ^{MT}	1	\$	2,641.00	
106	FRONT AIR DUCT DASHBOARD 2 ✓ ^{OR}	1	\$	5,901.00	
107	FRONT WINDSCREEN DEFROSTER NOZZLE - RH [?]	1	\$	185.00	
108	FRONT WINDSCREEN DEFROSTER NOZZLE - RH [?]	1	\$	137.00	
109	FRONT MOULDED HEADLINER ✓ ^{CR4}	1	\$	2,306.00	
110	FRONT A-PILLAR TRIM - LH / RH [?]	2	\$	458.00	
111	FRONT B-PILLAR TRIM - UPPER LH / RH [?]	2	\$	520.00	
112	FRONT D-PILLAR TRIM - LH / RH [?]	2	\$	470.00	
113	FRONT C-PILLAR TRIM - LH / RH [?]	2	\$	332.00	
114	FRONT & REAR FOLDING GRAB HANDLE - LH / RH [?]	4	\$	662.00	
115	FRONT THREE-POINT AUTOMATIC SEAT BELT - LH / RH [?] ⁽²⁾ ✓ ^{Ind}	2	\$	2,454.00	
116	FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH [?]	2	\$	383.00	
117	FRONT AIRBAG CONTROL UNIT ✓ ^m	1	\$	2,364.00	
118	FRONT AIRBAG CRASH SENSOR ✓ ^{nc}	3	\$	1,344.00	
119	FRONT CENTRAL PROTECTION ✓ ^{nl}	1	\$	590.00	
120	FRONT ALUMINIUM RIM (L4) ✓ ^{OR}	1	\$	1,889.00	
SUB TOTAL SPARE PARTS			\$	35,746.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
121	RUBBER VALVE / MC ?	1	\$	4.00	
122	FRONT ASSEMBLY CARRIER ?	1	\$	2,096.00	
123	FRONT CONSOLE - LH ?	1	\$	523.00	
124	FRONT GEARBOX SUPPORT ?	1	\$	90.00	
125	FRONT GEARBOX MOUNTING ?	1	\$	235.00	
126	FRONT WISHBONE LINK - LH ?	1	\$	605.00	
127	FRONT SUSPENSION GUIDE - LH ?	1	\$	1,057.00	
128	FRONT & REAR UPPER GUIDE - LH ?	2	\$	1,150.00	
129	FRONT WHEEL BEARING HOUSING - LH ?	1	\$	1,070.00	
130	FRONT SWIVEL JOINT - LH ?	1	\$	214.00	
131	FRONT WHEEL HUB - LH ?	1	\$	498.00	
132	FRONT FLANGE DOUBLE ANGLED BALL BEARING - LH ?	1	\$	273.00	
133	FRONT BEARING WHEELHUB - LH ?	1	\$	884.00	
134	FRONT SUSPENSION FORKS - LH ?	1	\$	293.00	
135	FRONT COUPLING ROD ?	2	\$	258.00	
136	FRONT ANTI-ROLL BAR MARKED GREEN ?	1	\$	478.00	
137	FRONT CONSTANT VELOCITY JOINTS DRIVE SHAFT ?	1	\$	2,999.00	
138	FRONT GAS SHOCK ABSORBER ?	1	\$	342.00	
139	FRONT STEERING RACK ?	1	\$	7,318.00	
140	FRONT TRACK ROD - LH ?	1	\$	109.00	
SUB TOTAL SPARE PARTS		:	\$	20,496.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
141	FRONT TIE ROD END - LH ?	1	\$	217.00
142	FRONT LOWER NOISE INSULATION ? - BR	1	\$	640.00
143	FRONT CONNECTING PLATE - LH ? ✓ DD	2	\$	520.00
144	FRONT FUSE HOLDER AND RELAY PLATE SUPPORT - LH ?	1	\$ - BR	53.00
145	FRONT UNDERBODY TRIM - LH ?	1	\$	51.00
146	FRONT NO PLATE ✓ ne	S/N	\$	60.00
147	ARCYLIC SEALANT ✓ ne	S/N	\$	180.00
148	CAVITY WAX - ne	S/N	\$	140.00
149	STONE CHIP ✓ ne	S/N	\$	180.00
150	METAL FILLER POWDER - ne	S/N	\$	280.00
151	FRONT WINDSCREEN SEALANT - ne	S/N	\$	200.00
152	LHS FRONT TYRE ✓ CRN	S/N	TBC	
153	SUNDRIES ?		\$	1,000.00
TOTAL SPARE PARTS		:	\$	106,818.00
TOTAL LABOUR CHARGES		:	\$	43,304.00
GRAND TOTAL		:	\$	150,122.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Star (LKK)
1/8/22, 4.7p

OP-M AL
EXcess?

P/P
5 PL y
20 dy 5

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/07/2022 14:42 (SGT)
Reported by Driver
Date of Accident 27/07/2022 20:00 (SGT)
Exact Location of Accident 36 Mimosa Rd, Singapore 807998
Additional Location Information 36 MIMOSA ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMW6617G
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner DINESH KUMAR S/O TEVERMUTHU
NRIC No SXXXX731E
Email Address DINESH.TEVER@GMAIL.COM
Mobile Phone No (Phone) +65-97364753
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Audi
Model A5
Variant SPORTBACK 2.0 TFS
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1984

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number 2070165966-01

DRIVER

Name of Driver K RAVEENA
NRIC No SXXXX047B
Date Of Birth 18/09/1988
Occupation Indoor

Date of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

20/04/2009
 13 YEARS AND 3 MONTHS
 Female
 (Phone) +65-98185714
 -
 RAVEENA.SMILES@GMAIL.COM
 ANG MO KIO STREET 44, BLK 455A
 #31-03
 561455
 No
 Spouse
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Head to Rear
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other vehicle or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?
 Translator's name
 Translator's ID
 Translator's phone number
 Translator's email
 Original language used in the statement

No
 2
 Yes
 No
 Yes
 2
 No
 -
 -
 -
 -
 -

PASSENGER 1

Name
 Gender

AARAV DINESH TEVER
 Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

THE DRIVER OF THE VEHICLE WAS FEELING LETHARGIC AFTER A LONG DAY AT WORK. AFTER TURNING OUT OF THE CARPARK INTO MIMOSA ROAD, THE DRIVER ACCIDENTALLY PRESSED THE ACCELERATOR INSTEAD OF THE BRAKE CAUSING THE CAR TO CRASH AT THE BACK OF A STATIONARY VEHICLE OUTSIDE THE RESIDENCE OF 36 MIMOSA ROAD.

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?

Yes
 Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Manufacturer

SLW6484J
 Mitsubishi

Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Eclipse cross
-
Gray
Private car
SIA SIONG LIM
(Phone) +65-96573809
-
-
-
-
-
-
0

INJURED PERSONS DETAILS

INJURED 1

Name of injured person K RAVEENA
Gender Female
Phone No (Phone) +65-98185714
Address -
Address Complement -
Post Code -
Approximate Age Years Old -
Injuries Sustained -
Injured person in which vehicle? SMW6617G
Were seat belts worn? Yes
Was this injured conveyed to hospital by ambulance? No

IMPORTANT NOTICE

SKETCH PLAN


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes, mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time 28/07/2022


Driver's Signature (if driver is not the policyholder) / Date & Time 28/07/2022


Witnessed by Reporting Centre Personnel Tony Fong

Sketch Plan




Describe Circumstances of the Accident

Driver of the vehicle was feeling lethargic after a long day at work. After turning out of the carpark into Mimosa Road, driver accidentally pressed the accelerator instead of the brake and causing car to crash at the back of parked stationary vehicle outside the residence of 26 Mimosa Road.

Declaration

I/We declare the foregoing particulars are true in every respect

 28/03/2022
Policyholder's Signature / Date & Time

 28/03/2022
Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel: 