

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.29899 Date: 19th Sep 2022

Our Ref: CS3/ASM22001124/Gcy3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLZ 3544Z

INSURED VEHICLE: SH 2934A ACCIDENT DATE: 06/02/2022

We thank you for your instruction on 01/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLZ 3544Z from M/s United Appraisal And Management Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLZ 3544Z and SH 2934A.
- c) Final Repair Bill of SLZ 3544Z from M/s Speedwerkz Pte Ltd.
- d) Colour damaged vehicle photographs of SLZ 3544Z.

Pre-Repair Inspection Date: 07/02/2022 at M/s Speedwerkz Pte Ltd, 13 Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLZ 3544Z

Make & Model : Toyota Vios E (Auto)

Year of Registration : 2018

Chassis Number : MR2B23F3001122155

Engine Capacity : 1496 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.