.OMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHB6213H

DATE:

01.08.22

MAKE

(F er

TOYOTA PRILIS

MVA JUMANI DOA: 28 07 22

NTUC WSUM)

MODEL	PRIUS		DOA:	28.07.22	NTUC (
Qty	Parts Description/ Labou	r	Туре	Unit Price	Amount	
	FRT FENDER LH				x \$1,111.93	1
.1	1 FRT FENDER EMBLEM LH			N	\$86.50	7
1	REAR DOOR ASSY LH				\$1,258.30	
1	FRT DOOR ASSY LH			<i>f</i>	\$1,264.00	1
1	REAR BUMPER ASSY			k	\$503.04	
1	REAR BUMPER SIDE BRACKET LH			un	17	
1	REAR BUMPER CLIPS			WM &		
			ı			
		,,		· >		
		CUID TOTAL			£4.240.57	
		SUB TOTAL			\$4,340.57	ļ
	Disco	LESS 25%			\$1,085.14	1
	DISCO	UNTED TOTAL	Y		\$3,255.43	
	FRT DOOR COMFORT LOGO	LKK Auto Cons			¢75.00	
	REAR DOOR APPS LOGO	the Repairer of To resurvey before		J	7/3.00	4
	PATROL STICKER	To display damage	ed part(s) durin	ng resurvey	\$60.00	NE
	BUMPER MAT	Parts prices are s	ubject to confir	mation(07) 166'54	\$50.00	NE
	BOWIFER WAT	Third party survey No illegal modifications		ed ININ	× \$50.00	
		Supplementary its	em(s) must be		\$235.00	
	Labour Charge	Acknowledged by F	Panairos			
	PANEL BEATING	Signature:	/chailei	52	\$ \$1,400.00	
	SPRAY PAINT	Date:		_	\$1,200.00	75
	REMOVE / REFIX DOOR PARTS		D:		\$240.00	1,5
	TUFF KOTE				\$50.00	
	ADVERTISEMENT LOGO			15+5 au	\$450.00	Şο
	T.C	TAL LABOUR		1741.50		
		TAL LABOUR			\$3,340.00	
	ECTI	MATE TOTAL	İ	1/53/400		
		MATE TOTAL		2(5\$1400 33ays	\$6,830.43	
	Tanfhi 13415749 W/ 18177 @ 5/20 215 Normy after upon 2-3clup			NE TO THE	==:	
	1 W/77 6 3	p~		.6 0		
	Ils Nemy after wepen	2-3db	,			
	This is an initial estimate based on a visual i	inspection of the a	bove vehic	le. The final repair qua	ntum will	
	be prepared after the vehicle is surveyed by	y,a motor Survevo	r appointe	by the insurance com	inany	
	tenth e library	Lucia		, and modifice com	pariy.	