



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007348/Evy3e2	
			Date: 17/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGW 3050G	Veh. Inspected	SJD 9090R
	Policy No.	D22MTPV01011068	Coverage (\$)	0.00
	Claim No.	CMTD2202593/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	02/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180K	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	WDD2040462A107520	Colour	BLACK
	Odometer	201135 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R15	GOODYEAR	4 mm
	L/H Front Tyre	205/55 R15	GOODYEAR	4 mm
	R/H Rear Tyre	205/55 R15	GOODYEAR	4 mm
	L/H Rear Tyre	205/55 R15	GOODYEAR	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/07/2022	Inspection Date	03/08/2022
	Survey held at	MTM PERFORMANCE AUTO PTE. LTD. 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB SINGAPORE 608586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	