

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: **SHA1618L**
Party At Fault: **UNKNOWN**

Ref. No:
Date of Loss: 01/08/2022
Driveable? YES

Make/Model: HYUNDAI I40, 1.7 L CRDI AT ABS
AIRBAG 4DR (A)
Vehicle Colour: BLUE
Engine No: D4FDGU695425
Odometer: 663110 KM

Vehicle Reg. Date: 22/12/2016
Gen Condition: GOOD
Chassis No: KMHLB41UMHU097268

Paint Type:
List Item Discount: 20.00 %
Total Loss? **NO**
Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	2,925.68
Miscellaneous Items	11.00
Labour	1,260.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,196.68
+ GST 7.00% (S\$)	293.77
Nett Amount (S\$)	4,490.45

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2022)**Parts:** 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA1618L/02/08/2022 08:58**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER X Repair	20.00	0.00	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET LH X	20.00	0.00	*44.80 FL
3	1		*FRONT BUMPER GRILLE LH X	20.00	0.00	*187.20 FL
4	10		*FRONT BUMPER CLIPS X	20.00	0.00	*22.00 FL
5	1		*FRONT FENDER LH X Repair	20.00	0.00	*663.00 FL
6	1		*FRONT FENDER SHIELD LH X	20.00	0.00	*174.90 FL
7	1		*HEADLAMP LH X	20.00	0.00	*1,388.00 FL
8	1		*FRONT FENDER ADVERTISEMENT	0	0.00	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**3,632.10****- List Item Discount on L Items (\$\$)****706.42****Total Parts (\$\$)****2,925.68**

ComfortDelGro Engineering Pte Ltd/SHA1618L/02/08/2022 08:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer) /	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	280 600.00
2	SPRAY PAINTING	New	500 600.00
3	CHECK LIGHTING FRONT	New	MX 60.00
Gross Labour Cost (S\$)			1,260.00

ComfortDelGro Engineering Pte Ltd/SHA1618L/02/08/2022 08:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 Days.

4/5

After repair photos.

One Qiang

02/8/22 4:30pm.