



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22007356/Kcy3e2 Date: 22/12/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 5032P	Veh. Inspected	GBF 6202P
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC00/025998	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	02/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR (M)	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JN1SC2F24Z0859152	Colour	METALLIC GOLD
	Odometer	297549 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	7 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	7 mm
	R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	8/8 mm
	L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/07/2022	Inspection Date	03/08/2022
	Survey held at	H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	