

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2022)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC7357P/01/08/2022 09:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	394.80 FL
4	2		*REAR BUMPER REINFORCEMENT STAY LH/RH	20.00	0.00	276.20 FL
5	10		*REAR BUMPER CLIPS	20.00	0.00	22.00 FL
6	1		*BOOTLID COVER	20.00	0.00	2,549.70 FL
7	1		*BOOTLID LOCK UPPER	20.00	0.00	224.00 FL
8	1		*BOOTLID H EMBLEM	20.00	0.00	38.00 FL
9	1		*BOOTLID IONIQ EMBLEM	20.00	0.00	31.80 FL
10	1		*BOOTLID HYBRID EMBLEM	20.00	0.00	24.30 FL
11	1		*REAR BUMPER FOG LAMP	20.00	0.00	201.50 FL
12	1		*REAR BUMPER LAMP LH/RH	20.00	0.00	85.30 FL
13	1		*REAR BUMPER HOOK COVER	20.00	0.00	94.60 FL
14	1		*REAR ANTENNA SMART KEY	20.00	0.00	40.50 FL
15	1		*REAR END PANEL	20.00	0.00	532.00 FL
16	2		*REAR BUMPER BRACKET LH/RH	20.00	0.00	111.60 FL
17	1		*REAR NUMBER PLATE W/HOLDER	20.00	0.00	55.00 FL
18	1		*BOOTLID COMFORT APP STICKER	20.00	0.00	40.00 FL
19	1		*BOOTLID COMFORT/TEL NO. STICKER	20.00	0.00	60.00 FL
20	1		*REAR REVERSE SENSOR	20.00	0.00	180.00 FL
21	2		*SEALANT WSCREEN	20.00	0.00	46.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,917.95
- List Item Discount on L Items (\$)	1,183.59
Total Parts (\$)	4,734.36

ComfortDelGro Engineering Pte Ltd/SHC7357P/01/08/2022 09:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3117.05

20% - 2493.64

SN 381

2874.64

Repairer Estimates

9:48 AM

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			11.00

11

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	525 1,050.00
2	SPRAY PAINTING	New	500 600.00
3	REMOVE/REFXI UPPER WINDSCREEN & LOWER GLASS	New	180 200.00
4	CHECK WIRING AND LIGHTING	New	30 60.00
5	REMOVE/REFXI REVERSE SENSOR	New	30 60.00
6	TUFF COATING	New	30 60.00
Gross Labour Cost (\$)			1295 2,030.00

ComfortDelGro Engineering Pte Ltd/SHC7357P/01/08/2022 09:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpik 97445749
WP 1/8/27C 430pm
2 days
4/3 Resurvey after repair
Tanpik e/khanbun
2874-64
11
1295
4180.64
4/5 3350
2 days
#

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: