



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: CHRYLLIS QUAH

Ref: CS/INC22007367/Uqy3e2

Date: 16/08/2022

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SKS 9979L	<b>Veh. Inspected</b>	SKP 5671R
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1182267-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	DIANA TAY	<b>Assign Date</b>	02/08/2022

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	MAZDA 3 (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2014
<b>Chassis No.</b>	JM6BM42A8F0144487	<b>Colour</b>	BLACK
<b>Odometer</b>	99491 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	205/60 R16	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	YOKOHAMA	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	29/07/2022	<b>Inspect Date / Time</b>	02/08/2022 ( 12:05 PM )
<b>Survey held at</b>	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**