



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007374/Uvy3q2	
			Date: 12/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKZ 557T	Veh. Inspected	SJZ 8650R
	Policy No.	D22MTPV01000844	Coverage (\$)	0.00
	Claim No.	CMTD2202613/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	02/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA STREAM (A)	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	RN61036928	Colour	BROWN
	Odometer	283540 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	FIRENZA	6 mm
	L/H Front Tyre	225/45 R17	FIRENZA	6 mm
	R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/07/2022	Inspection Date	03/08/2022
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	