



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007374/Uvy3	
			Date: 02/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKT 557T	Veh. Inspected	SJZ 8650R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202613/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	02/08/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	26/07/2022	Inspection Date	03/08/2022
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			