



Champion Motors

Inchcape

Co. Reg No. : 195000068E
GST Reg No. : MR-8500000-9
No. 2 Pandan Crescent
Singapore 128462 Tel: 66311855



Attn: Steve

6 days. Final Bill

ACCOUNT INVOICE

Account Details			Account No.		Customer Details		
ECICS Limited 7 Temasek Boulevard, #10-01 Suntec Tower One Singapore 038987			S8000026 / ECICS		Mdm Savadi Gauri Prakash 132 Tanjong Rhu Road #16-12 Singapore 436919 Mobile: 90067508		
			Document No. 82002087				
			Document Date 21/09/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	JIMNY	6GG1BHH35	16/08/2019	SMN5375H	63274	12189	65DS/SMN5375H
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JSAGJB74V00116713		K15B1028692	60	Francis Cher T S	10/08/2022	10.28	21/09/2022 9.33
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS. : ECICS INS. T/P VEH. : SJC9472C ACC DATE : 27.07.22 BY : STEVE (LKK)	*	50.00		50.00	
2	S	S-EURO-001 SUPPLY NUMBER PLATE (FRT WITH CASING)	0263	80.00		80.00	
3	S	S-BMS RESET AND REPROGRAMME ECU.		146.50		146.50	
4	S	S-BMS REPLACE AND REFOCUS HEADLAMP.		293.00		293.00	
5	S	S-BMS REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, R/F FENDER, FRT SUPPORT PANEL, R/F DOOR AND AFFECTED PORTION OF CAR.		1758.00		1758.00	
6	S	S-BMS SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		968.00		968.00	
7	1	S35100-77RA0-000 HEADLAMP ASSY,R	1.00	1242.15		1242.15	
8	2	S35500-54P00-000 LAMP ASSY,FOG AND DRL	1.00	216.55		216.55	
9	3	S58200-78R00-000 PANEL,FR OUTER	1.00	505.65		505.65	
10	4	S58611-78R00-000 PANEL,FR FENDER,R	1.00	142.95		142.95	
11	5	S72320-78R00-000 LINING COMP,FRONT FENDER,R	1.00	60.50		60.50	
For & on behalf of Champion Motors (1975) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Champion Motors

inchcape

Co. Reg No. : 195000068E
GST Reg No. : MR-8500000-9
No. 2 Pandan Crescent
Singapore 128462 Tel: 66311855



ACCOUNT INVOICE

Account Details			Account No.		Customer Details				
ECICS Limited 7 Temasek Boulevard, #10-01 Suntec Tower One Singapore 038987			S8000026 / ECICS		Mdm Savadi Gauri Prakash 132 Tanjong Rhu Road #16-12 Singapore 436919 Mobile: 90067508				
			Document No. 82002087						
			Document Date 21/09/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	JIMNY	6GG1BHH35	16/08/2019	SMN5375H	63274	12189	65DS/SMN5375H		
Chassis No.		Engine No.	Terms	SA / Counter		Vehicle In		Collected On	
JSAGJB74V00116713		K15B1028692	60	Francis Cher T S		10/08/2022	10.28	21/09/2022 9.33	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
12	6	S71711-78R10-5PK BUMPER,FRONT				1.00	450.70		450.70
13	7	S72110-78R01-C48 GRILLE,RADIATOR				1.00	313.30		313.30
14	8	S71721-78R00-5PK NET,FRONT BUMPER				1.00	34.65		34.65
15	9	S71713-78R00-5PK GARNISH,FR BPR LICENSE(BLACK)				1.00	39.60		39.60
16	0	S77511-78R00-5PK GUARD,FR FNDR SPLASH,R(BLACK)				1.00	107.20		107.20
17	1	S77512-78R00-000 PROTECTOR,FR FENDER SPLASH				1.00	20.35		20.35
18	2	S71631-57M00-000 BOLT,1ST MOUNTING				1.00	4.65		4.65
19	3	S39120-77R10-000 HOSE ASSY,HEADLAMP CLEANERNO2				1.00	151.70		151.70
20	4	S39153-77R00-000 CASE ASSY,HEADLAMP CLEANER				1.00	13.40		13.40
21	5	S35526-78R00-000 BRACKET,FOG LAMP,R				1.00	36.30		36.30
22	6	S72382-78R00-000 SHROUD,RADIATOR LWR				1.00	71.50		71.50
23	7	S36717-77R02-000 COVER,RELAY BOX				1.00	16.85		16.85

For & on behalf of Champion Motors (1975) Pte Ltd		Customer's Signature		Charge Summary		Total 6,723.50	
		Please acknowledge receipt of vehicle		Parts 3,428.00		GST 7.00% 470.65	
				Labour 50.00		Less 0.00	
				Sublet 3,245.50			
				Lubrication/Fluid 0.00			
				Others 0.00		Amount Due 7,194.15	

Company Copy