

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/07/2022
Vehicle Reg. No.:	SHC2353H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	13/12/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2F85892	Chassis No:	JTDKB3FU003090067
Odometer:	215922 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,704.43
Miscellaneous Items	11.00
Labour	1,620.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,335.43
+ GST 7.00% (S\$)	233.48
Nett Amount (S\$)	3,568.91

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2022)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue: Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC2353H/02/08/2022 13:30**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>X repair</i>	25.00	0.00	*591.75 FL
2	1		*FRONT BUMPER BRACKET RH <i>X</i>	25.00	0.00	*77.00 FL
3	1		*FRONT BUMPER PROTECTOR RH <i>X</i>	25.00	0.00	*127.70 FL
4	1		*FRONT FENDER RH <i>X repair</i>	25.00	0.00	*1,111.93 FL
5	1		*FRONT FENDER EMBLEM RH <i>X</i> NA <i>X NN</i>	25.00	0.00	*86.50 FL
6	1		*FRONT WHEEL CAP RH <i>cut</i>	25.00	0.00	*177.70 FL ✓
7	1		*FRONT DOOR COMFORT STICKER <i>Auto Cent</i>	0	0.00	*75.00 FS ✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

2,247.58

- List Item Discount on L Items (\$\$)

543.15

Total Parts (\$\$)

1,704.43

ComfortDelGro Engineering Pte Ltd/SHC2353H/02/08/2022 13:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

133.27

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer) ✓	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 700.00
2	SPRAY PAINTING	New	750 800.00
3	CHECK LIGHTING	New	W/X 60.00
4	RESET WHEEL ALIGNMENT	New	X 60.00
Gross Labour Cost (S\$)			1,620.00

ComfortDelGro Engineering Pte Ltd/SHC2353H/02/08/2022 13:30. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 Days

Paint by prt.

Before paint photos

Eric Qiang

02/8/22 4:30 pm

1319.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: