

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Co. & GST Reg. No.: 199902271W

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:31

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85017991 Date : 25/11/2022 Order : SNA2262B Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No: SNA2262B (V 49365)		Regn Date: 12/06/2021	Mileage: 21378	WIP No.: 35375	
Model: A3 SPORTBACK 1.5 TFSI 8YAAZG		Chassis: WAUZZZGY7MA095134	Engine: DFY 268691	Dept: U	
You have been assisted by :- UB-Lim Kee Siang (43)					
		Details	Qty	Unit Price	Amount
S	SUBLET	M: BNP - TO SUPPLY VEHICLE NUMBER PLATE	60.00	1.00	60.00
Q	EXC	M: 8888 Insurance Excess/Liability	-400.00	1.00	-400.00
S	BODYWORK	M: TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	500.00	1.00	500.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	1400.00	1.00	1,400.00
S	BODYWORK	M: TO CARRY OUT VACUUM AND REGAS FOR R1234	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET.TO REPAIR BOTH FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	2750.00	1.00	2,750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,HINGES AND BOTH FRONT FENDER	2475.00	1.00	2,475.00
S	BODYWORK	M: TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	384.00	1.00	384.00
X	A8Y0807065A GRU	COVER Less 020%	1.00	1677.00	1,341.60
X	A8Y0807647 9B9	GRILLE Less 020%	1.00	432.50	346.00
X	A8Y0807233	PLATE-A/P GT Less 020%	1.00	265.00	212.00
X	A8Y0807110 GRU	SPOILER-A/P GT Less 020%	1.00	325.50	260.40

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Co. & GST Reg. No.: 199902271W

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 11:31

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85017991 Date : 25/11/2022 Order : SNA2262B Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SNA2262B (V 49365) Regn Date: 12/06/2021 Mileage: 21378 WIP No.: 35375

Model: A3 SPORTBACK 1.5 TFSI 8YAAZG Chassis: WAUZZZGY7MA095134 Engine: DFY 268691 Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)

			Details		Qty	Unit Price	Amount
X	A8Y0807533	9B9	COVERSTRIP-A/P GT	Less 020%	1.00	103.50	82.80
X	A8Y0807534	9B9	(A) (SK) (4) COVERSTRIP	Less 020%	1.00	103.50	82.80
X	A8Y0807681A	9B9	GRILL-A/P GT	Less 020%	1.00	170.50	136.40
X	A8Y0853651D	9B9	GRILLE	Less 020%	1.00	932.00	745.60
X	A8Y0853949	9B9	PLATE	Less 020%	1.00	210.00	168.00
X	A8Y0807550		FOAM INSER	Less 020%	1.00	119.50	95.60
X	A8Y0807109		BRACKET	Less 020%	1.00	747.50	598.00
X	A8Y0807333A		(A) (SK) (4) SUPPORT-15	Less 020%	1.00	9.70	7.76
X	A8Y0807334A		(A) (SK) (4) SUPPORT-15	Less 020%	1.00	9.70	7.76
X	A8Y0121285		001374/ (V) (SK) (LAST)	Less 020%	1.00	92.50	74.00
X	A8K0010520G		STICKER	Less 020%	1.00	15.50	12.40
X	A8V0010515		STICKER	Less 020%	1.00	8.30	6.64
X	A8Y0823029		(A) (SK) (6) HOOD-15/08	Less 020%	1.00	3271.00	2,616.80
X	A8Y0823126		001374/ (V) (SK) (LAST)	Less 020%	1.00	29.50	23.60
X	A8Y0941033A		001374/ (V) (SK) (LAST)	Less 020%	1.00	4084.00	3,267.20
X	A8Y0941034A		(V) (GER) HEADLIGHT	Less 020%	1.00	4084.00	3,267.20
X	A8Y0955453B		001374/ (V) (GER) WATER	Less 020%	1.00	179.00	143.20
X	A8Y0805588A		CARRIER	Less 020%	1.00	990.00	792.00
X	A5WA816411D		001378/ (V) (GER) CONDE	Less 020%	1.00	568.50	454.80
X	AG 12E050M2		COOLANT -35°C	Less 020%	6.00	49.40	237.12
X	A8Y0121283M		(A) (SK) (3) AIR DUCT-A	Less 020%	1.00	41.10	32.88
X	A8Y0121284M		(A) (SK) (5) AIR DUCT-A	Less 020%	1.00	41.10	32.88
X	A82A121230		001378/ (V) (GER) SEAL-	Less 020%	1.00	13.90	11.12
X	A8Y0121345		001374/ (V) (GER) AIR D	Less 020%	1.00	58.30	46.64
X	A5Q0129954H		COVER	Less 020%	1.00	29.80	23.84
X	A5Q0129254K		(A) (SK) AIR DUCT-A/P	Less 020%	1.00	58.10	46.48
X	A5QA129621C		(A) (SK) AIR DUCT-A/P	Less 020%	1.00	35.10	28.08
X	A5Q0129607AQ		(A) (SK) AIRCLEANER-A/	Less 020%	1.00	336.50	269.20
X	A5Q0129747B		001378/ (V) (SK) (LAST)	Less 020%	1.00	26.70	21.36
X	A8Z0820535B		TEMP.SENS.-A/P GT	Less 020%	1.00	64.00	51.20
X	AN 90558401		RIVET (AP GT)	Less 020%	5.00	3.80	15.20
X	A8K0820536E		001401/ (V) (SK) BRACKE	Less 020%	1.00	20.40	16.32

Parts 15,574.88
Labour 0.00
Sublet 9,249.00
Menus 0.00
Lubricant 0.00

Sub-Total 24,423.88

7% GST 1,709.67

Grand Total 26,133.55



Received by

For & on behalf of
Premium Automobiles Pte Ltd