



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22007392/Dny3e2 Date: 22/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 88H	Veh. Inspected	SLD 7227D
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/07/22/5054	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	03/08/2022
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP32050C864915	Colour	BLUE
Odometer	133663 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/35 R20	PIRELLI	5 mm
L/H Front Tyre	255/35 R20	PIRELLI	5 mm
R/H Rear Tyre	285/30 R20	MICHELIN	5 mm
L/H Rear Tyre	285/30 R20	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/07/2022	Inspection Date	03/08/2022
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #02-16 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	