

ASS. REC. BY:

REF:

OS/SMR 22007392/Dny³

ASSIGNMENT

CUB Jan 2021

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLD 7227D Yr Regn: 2011 March
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 523i cc 2497
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 133663 T/Radio: Insured / Std / NI / NA
 Eng/No: 08217702N52B25AF
 C/No: WBAFP32050C864915
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD. ARim or
 Tyre Size: F: 255 / 35 R20
 R: 285 / 30 R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Pirelli Rear Michelin
 R/Bal: S mm R/Bal: S mm
 L/Bal: S mm L/Bal: S mm
 D.O.A. 29/07/2022 D.O.I. 03/08/2022
 Survey held at CS Ong AMK
 Des. of Damages: Fri / Rear / O/S / NIS / UIC / Rooftop or
H/S Prot
 The UIC / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. of Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24-HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	SMRT SMB 88H
	MV 951C
	LTA 361C
	HL 591C
18/11/22	price 2/3 6,800/- with 5 days July (Red. 43779.91, 870%)

Date/Time, File Pass to?

1) 22/11/22

Date/Time, File Return to?

2)

: Prel. Report
 : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Report Format:

Lump Sum / I.B.J: (\$ 6800)

Add Fee: : Site Insp. (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
\$ - \$ - \$	
Photos	
Others	
TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	090A
Vehicle Details	
Vehicle No.:	SLD7227D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Aug 2022
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	08217702N52B25AF
Chassis No.:	WBAFP32050C864915
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$46,250.00
Original Registration Date:	30 Mar 2011
First Registration Date:	30 Mar 2011
Transfer Count:	2
Actual ARF Paid:	\$46,250.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2031
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$42,683.00
COE Rebate Amount:	\$36,269.00
Total Rebate Amount:	\$36,269.00

The information contained herein is correct as at 01 Aug 2022

OK



01/2031)

Road tax valid till Feb 2023, view to believe it, all wear and tear being replaced, no repair needed, invoice attached for your reference. L...

Posted: 28-Jul-2022

PREMIUM AD



BMW 5 Series 523i (COE till 09/2030)

\$98,888

\$12,100 /yr

17-Feb-2011

2,497 cc

140,000 km

Luxury

Available

Cruise around in this renowned German luxury sedan! Spacious cabin and beautiful interior! Wear and tear done with receipts! Superb c...

Posted: 04-Jun-2022

PREMIUM AD



BMW 5 Series 523i (COE till 12/2030)

\$99,800

\$11,850 /yr

22-Feb-2011

2,497 cc

126,400 km

Luxury

Available

Well maintained unit, comes with lots of mods, 10 inch Android unit, newly upholstery leather seats, 20 inch sport rims with 6/4 pot Bre...

Precision Automobile Pte Ltd

Posted: 29-Jul-2022

PREMIUM AD



BMW 5 Series 523i (COE till 01/2031)

\$94,800

\$11,140 /yr

25-Feb-2011

2,497 cc

124,610 km

Luxury

Available

Drive With Assurance With 5 Star Reviews At 2.88% Army Owner Classic Black Superb Condition Original Paint No Repair Needed Beautif...

Posted: 31-Jul-2022



BMW 5 Series 523i Highline (COE till 12/2030)

\$98,800

\$11,730 /yr

25-Feb-2011

2,497 cc

112,000 km

Luxury

Available

2 years warranty on engine and gearbox! Full loan at only 3.xx%! Upgraded M5 Bodykit With Misano Blue paintwork matched on brown...

San Hup Bee (S) Pte Ltd

Posted: 15-Jul-2022

PREMIUM AD



BMW 5 Series 523i (COE till 09/2030)

\$97,800

\$11,970 /yr

28-Feb-2011

2,497 cc

94,000 km

Luxury

Available

\$0 downpayment available. 1 owner only. Agent PML maintained and service regularly with proof. 2 more free servicing available at agen...

SmartCars Boutique Pte Ltd

Posted: 01-Aug-2022

PREMIUM AD



BMW 5 Series 523i (COE till 02/2031)

\$98,800

\$11,510 /yr

01-Mar-2011

2,497 cc

120,000 km

Luxury

Available

newly fitted M5 bodykit with new ceramic white paintwork! High spec unit with paddle shifters, Sunroof and electric tailgate! New valve...

Precise Auto Trading Pte Ltd

Posted: 23-Jul-2022

PREMIUM AD



BMW 5 Series 523i (COE till 01/2031)

\$96,800

\$11,380 /yr

03-Mar-2011

2,497 cc

106,300 km

Luxury

Available

All Wear And Tear Replaced With Receipts,100% Loan Available,Ex-bankruptcy And Bad Credit Welcome,High Trade In.

Faster Auto Trading

Posted: 14-Jul-2022



BMW 5 Series 523i (COE till 03/2031)

\$105,800

\$12,290 /yr

11-Mar-2011

2,497 cc

145,173 km

Luxury

Available

United Motoring Pte Ltd

Posted: 15-Jul-2022

PREMIUM AD



BMW 5 Series 523i (COE till 01/2031)

\$97,800

\$11,500 /yr

14-Mar-2011

2,497 cc

213,000 km

Luxury

Available

Bank and in house available, high approval rate, low and attractive interest rates, high trade in, super well maintained by previous doctor...

Posted: 10-Jun-2022

PREMIUM AD



BMW 5 Series 523i (COE till 03/2031)

\$93,800

\$10,880 /yr

16-Mar-2011

2,497 cc

Luxury

Available

\$1068 monthly! 100% in house loan by GV Cars financing! 2.99% per annum. Add on 2 years warranty on engine and gearbox by GV M...

GV Automobile Centre Pte Ltd

Posted: 31-Jul-2022

PREMIUM AD

BMW 5 Series 523i (COE till 03/2031)

\$99,999

\$11,590 /yr

18-Mar-2011

2,497 cc

169,000 km

Luxury

Available

Compare

C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6481 1916

E-Mail: csongauto.claims@yahoo.com.sg

To: MS FIRST CAPITAL
Att: Motor Claims Dept

ACCIDENT INVOLVING SMB88H [YOUR INSURED] & SLD7227D [YOUR CLIENT] ON 29/07/2022.

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR COSTS FOR SLD7227D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET HH	\$ 2,348.55	X
1PC	BONNET INSULATOR HH	\$ 248.36	X
1PC	BONNET SEAL HH	\$ 101.50	X
1PC	HEAD LAMP LH <i>mondy broker</i> 2302.00	\$ 2,762.90	✓
1PC	HEAD LAMP LOWER BRACKET LH <i>broker</i> 289.60	\$ 369.15	✓
1PC	HEAD LAMP ECU LH HH	\$ 769.40	X
1PC	HEAD LAMP WIRE HARNESS HH	\$ 1,201.34	X
1PC	FRONT BUMPER HEAD LAMP NOZZLE CAP LH HH	\$ 103.15	X
1PC	FRONT BUMPER SIDE GRILLE LH HH	\$ 281.69	X
1PC	FRONT BUMPER SENSOR @ \$361.16 EACH HH	\$ 1,444.64	X
1PC	FRONT BUMPER SENSOR HOLDER @ \$65.39 EACH HH	\$ 261.56	X
1PC	FRONT BUMPER SENSOR WIRE HARNESS HH	\$ 930.00	X
1PC	FRONT BUMPER UNDER COVER HH	\$ 228.95	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$295.14 EACH HH	\$ 590.28	X
1PC	FRONT BUMPER SPONGE HH	\$ 395.60	X
1PC	FRONT REINFORCEMENT BAR HH	\$ 1,065.12	X
1PC	FRONT SUPPORT PANEL HH	\$ 3,180.00	X
1PC	FRONT FENDER LH <i>dyon</i>	\$ 1,288.16	X
1PC	FRONT FENDER INNER SHIELD LH HH	\$ 195.44	X
1PC	FRONT FENDER LAMP LH HH	\$ 480.90	X
1PC	FRONT FENDER LAMP CHROME GARNISH LH HH	\$ 316.70	X
1PC	FRONT WHEEL HOUSING LH HH	\$ 3,987.15	X
1PC	FRONT WHEEL BEARING & HUB ASSY LH <i>Dyon</i> 552.45	\$ 656.15	✓
1PC	FRONT KNUCKLE ARM LH <i>distml</i> 679.50	\$ 966.19	✓
1PC	FRONT LOWER ARM LH <i>distml</i> 425.00	\$ 548.15	✓
1PC	FRONT THRUST ARM LH HH	\$ 470.17	X
1PC	FRONT ABSORBER LH <i>distml</i> 522.30	\$ 698.95	✓
1PC	FRONT UPPER ARM LH HH	\$ 606.50	X
1PC	FRONT CONTROL ARM LH HH	\$ 520.17	X
1PC	FRONT STABILIZER LINK LH HH	\$ 231.20	X

IPC	FRONT STABILIZER BAR HH	\$ 574.30	X
IPC	FRONT TIE ROD LH HH	\$ 319.00	X
IPC	FRONT TIE ROD END LH HH	\$ 215.24	X
IPC	STEERING RACK & PINION ASSY HH	\$ 6,443.35	X

4,770.85
10% 4,293.76

PARTS SUM: \$ 34,799.91
 PARTS LESS 5%: \$ 1,740.00
 PARTS TOTAL: \$ 33,059.91

LABOUR & SPECIAL NETT ITEMS

- * TO SUPPLY HEAD LAMP STICKER HH \$ 400.00 X
- * TO SUPPLY IPC SPORT RIM cut 800.00 \$ 2,800.00 ✓
- * TO SUPPLY IPC TYRE cut 50% depre \$ 600.00 200/-
- * TO SUPPLY FRONT BUMPER (M5 BODYKIT) cut/money crnk 1700.00 \$ 3,000.00 ✓
- * TO SUPPLY FRONT BUMPER LOWER LID (M5 BODYKIT) SV2 \$ 2,000.00 X
- * TO SUPPLY FRONT BUMPER SIDE GRILLE HH \$ 1,000.00 X
- * TO SUPPLY FRONT BUMPER CLIPS Nec \$ 50.00 20/-
- * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HH 2720.00 \$ 50.00 X
- * TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS \$ 300.00 HH
- * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 3,000.00 600/-
- * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 3,000.00 500/-
- * TO TUFF COAT DAMAGED AREAS 1520.00 \$ 300.00 HH
- * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400.00 180/-
- * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120.00 60/-
- * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200.00 30/-
- * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS, RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS \$ 300.00 150/-

LABOUR & S/N TOTAL: \$ 17,520.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 50,579.91

03/08/2022 @ 1500

Not Avail

2 hrs 5 days.

7 yr 2kk and 2

8,533.76
4/5 6,800/-