



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 12/08/2022

Survey details

Date of loss	2/8/2022
Date of appointment	3/8/2022
Date of survey	4/8/2022
Location of survey	HONG MOTOR SERVICES

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SMF 5843R
Make and Model	HYUNDAI TL TUCSON FL 1.6 GLS T-GDI DCT 2WD
Date of registration	19/11/2018
Excess	
Market Value	\$103,000.00
Parf Rebate	\$35,182.00
Nett Loss	\$67,818.00

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	6 days (est)

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$4,000.00-\$5,000.00