



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : **SBS6384D**

Accident date : 30th Jul 2022

Model No : Mercedes

Registered owner : Go Ahead Singapore Pte Ltd

Citaro

Date of Estimate : 03/08/22

My Ref : **BF-IC-1082**

Total Charge

Parts changed (Total 2 days)

- | | | | |
|--|-----|------|-------------------|
| a) Replacement of shattered glass . P/N : 628 675 1510 ✓ BR | S\$ | 1020 | -10% = 918 |
| b) Labour for removal and Installation of new glass | S\$ | 600 | 450 |

Subtotal	S\$	1620	1368
----------	-----	------	-------------

Steve (LKK)
4/08/22, 12.00 pm
Without Prejudice
2 days
P/P
Resurvey Before spray

Total Charge :	S\$	1620
GST	S\$	113.4
Total Bill	S\$	1733.4

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg



BOXFRESH PTE LTD
WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611
OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880
T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg