

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0648/2022/EQ
DATE : 2-Aug-22
WIP : 35486

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. LEE MEI FEI
ADDRESS : 27 FERNVALE ROAD
#19-30
SINGAPORE 797415
TELEPHONE : HP +65 97855296
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220065304
VEHICLE NO : SLE 798 M
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 13/6/2022
ENGINE NO : DEM 034540
CHASSIS NO : WAUZZZF59NA002235
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Jul-22
PLACE OF ACCIDENT : KILLINEY ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 798 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 150	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 /	✓
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	✓
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$ 280.00 X	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT AND RHS UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 6 X 500	3000 ✓
SUB-TOTAL LABOUR CHARGES		: \$ 10,360.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 798 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS UPPER A-PILLAR AND RHS FRONT DOOR. 1/2	J-S \$ 550 6,000.00	1925 ✓ 4650
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$ 280.00	X
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 17,024.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 798 M

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$	2,493.00	✓ BR 1994.40
2	FRONT BUMPER SECURING STRIP	2	\$	79.00	63.20
3	FRONT BUMPER GRILLE - CENTER	1	\$	219.00	?
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$	293.00	NN ? X
5	FRONT BUMPER SPOILER	1	\$	599.00	?
6	FRONT AIR GUIDE - RH	1	\$	72.00	57.20
7	FRONT BUMPER CLOSING ELEMENT	1	\$	293.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$	151.00	120.40
9	FRONT BUMPER AIR GUIDE TRIM - RH / CENTER	2	\$	181.00	82.64
10	RADIATOR GRILLE	1	\$	1,881.00	1504.80
11	RADIATOR GRILLE COVER	1	\$	141.00	?
12	RADIATOR GRILLE BRACKET	1	\$	19.00	?
13	FRONT SECURING PLATE	1	\$	12.00	X NN
14	FRONT CAMERA	1	\$	1,264.00	X NN
15	FRONT BUMPER FOAM FILLER PIECE	1	\$	163.00	130.40
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$	899.00	719.20
17	FRONT BUMPER UPPER GUIDE SECTION - RH	1	\$	41.00	32.24
18	FRONT BUMPER TOP COVER	1	\$	143.00	?
19	CAUTION SIGN STICKER	1	\$	16.00	X NN
20	AIR CONDITIONER STICKER	1	\$	9.00	?
SUB TOTAL SPARE PARTS		:	\$	8,968.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST.
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 798 M

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER LOCK CARRIER BRACKET ? X NN	1	\$	154.00
22	FRONT BUMPER SUPPORT - LH / RH ? ✓ NEC	2	\$	64.00 51.04
23	POP RIVET ? ✓ NEC	4	\$	4.00 2.88
24	HORN LOW TONE - RH ? X NN	1	\$	139.00
25	HORN BRACKET - RH ? X NN	1	\$	33.00
26	FRONT PARKING AID SENSOR - OUTER / INNER / SIDE AS 1 \$ MIS	1	\$	798.00 212.40
27	FRONT PARKING AID SEAL RING ✓ NCC X NN	4	\$	10.00
28	FRONT BUMPER WIRING SET ? X NN	1	\$	449.00
29	FRONT FENDER - RH ✓ OK	1	\$	1,189.00 951.20
30	FRONT FENDER ATTACHMENT PARTS ? X NN	1	\$	55.00
31	FRONT FENDER CLOSING ELEMENT - RH ✓ BT	1	\$	83.00 65.84
32	FRONT FENDER BRACKET - RH ✓ BT	1	\$	41.00 32.72
33	POP RIVET ✓ NCC	6	\$	23.00 18.24
34	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH ? X NN	1	\$	55.00
35	FRONT FENDER BRACKET - LH ? X NN	1	\$	40.00
36	FRONT FENDER BRACE - RH ? ✓ BT	1	\$	132.00 105.20
37	FRONT FENDER TRIM - RH ✓ NCC	1	\$	171.00 136.40
38	FRONT FENDER WHEEL HOUSING LINER - RH ✓ MIS	1	\$	299.00 238.80
39	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ✓ BR 1 X NN	1	\$	176.00
40	FRONT WHEEL SPOILER - RH ✓ OK	1	\$	82.00 65.12
SUB TOTAL SPARE PARTS			\$	3,997.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 798 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT SPOILER TRIM- RH ✓ X NN	1	\$	40.00	
42	FRONT STONE CHIP GUARD - RH ✓ MC	1	\$	57.00	45.28
43	FRONT WHEEL SPOILER TRIM BRACKET TRIM - RH ? X NN	1	\$	27.00	
44	FRONT FENDER LEDGE COVER - LONG ? ✓ BR	1	\$	40.00	31.44
45	FRONT FENDER LEDGE COVER - RH SHORT ✓ MC	1	\$	18.00	13.92
46	HEADLIGHT TOP COVER - RH ✓ BR	1	\$	49.00	38.64
47	BONNET ✓ MC	1	\$	3,491.00	2792.80
48	BONNET ATTACHMENT PARTS ✓ NN	1	\$	128.00	
49	BONNET HINGE - LH / RH ? X NN	2	\$	932.00	
50	BONNET IMPACT PROTECTION - CENTER / LH / RH ✓ MC	3	\$	93.00	73.20
51	BONNET ENGINE SOUND ABSORBER ✓ CRV	1	\$	382.00	305.60
52	FRONT FENDER COVER - RH INNER X NN	1	\$	81.00	
53	BONNET GAS FILLED STRUT X NN	2	\$	256.00	
54	BONNET STRIKER - RH ? X NN	1	\$	56.00	
55	BONNET LID LOCK ? X NN	1	\$	228.00	
56	BONNET BOWDEN CABLE - CENTER ? X NN	1	\$	64.00	
57	BONNET BOWDEN CABLE COVER ? X NN	1	\$	11.00	
58	BONNET BOWDEN CABLE - CENTER ? X NN	1	\$	64.00	
59	BONNET RELEASE LEVER ? X NN	1	\$	15.00	
60	BONNET LOCK CABLE - RH ? X NN	1	\$	82.00	
SUB TOTAL SPARE PARTS			:	\$	6,114.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 798 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	FRONT PLENUM CHAMBER COVER - RH X NN	1	\$	108.00	
62	HEADLIGHT MATRIX BEAM - RH ✓ BR	1	\$	8,172.00	6537.60
63	HEADLIGHT HOSE ? ✓ TN	1	\$	42.00	32.88
64	HEADLIGHT COMPENSATING PIECE ? X NN	3	\$	137.00	
65	LIFT CYLINDER - RH ? X NN	1	\$	217.00	
66	LIFT CYLINDER BRACKET - RH ? ✓ BR	1	\$	17.00	12.88
67	LIFT CYLINDER HOSE ? ✓ BR	2	\$	160.00	127.60
68	WASH WATER RESERVOIR ? X NN	1	\$	154.00	
69	LOCK CARRIER ✓ CR4	1	\$	1,127.00	901.60
70	LOCK CARRIER SUPPORT - RH ? X NN	1	\$	43.00	
71	CHARGE AIR COOLER ? X NN	1	\$	654.00	
72	CHARGE AIR COOLER PRESSURE HOSE - RH ? X NN	1	\$	413.00	
73	A/C CONDENSER ? X NN	1	\$	683.00	
74	A/C CONDENSER BRACKET ? X NN	1	\$	21.00	
75	RADIATOR ? X NN	1	\$	699.00	
76	RADIATOR FAN RING ? X NN	1	\$	277.00	
77	RADIATOR CONTROL UNIT FAN ? X NN	1	\$	2,012.00	
78	RADIATOR AIR GUIDE - LH / RH ? X NN	2	\$	72.00	
79	RADIATOR AIR GUIDE - LH / RH ? X NN	2	\$	38.00	
80	RADIATOR AIR GUIDE - UPPER / LOWER ? X NN	2	\$	44.00	
			:	\$	15,090.00

SUB TOTAL SPARE PARTS

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 798 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	RADIATOR COOLANT / MC	6	\$	297.00	237.12
82	INTAKE AIR DUCT - RH ? X NN	1	\$	25.00	
83	INTAKE AIR DUCT AIR GUIDE ? X NN	1	\$	61.00	
84	INTAKE AIR DUCT AIR FILTER ? ✓ BR	1	\$	418.00	334.40
85	INTAKE AIR DUCT HOSE ? X NN	1	\$	110.00	
86	FRONT DOOR CHROME TRIM - RH X X NN	1	\$	171.00	
87	NOISE INSULATION - LOWER CENTER ? X NN	1	\$	640.00	
88	ROOF CHROME MOLDING - RH X X NN	1	\$	706.00	
89	FRONT WINDOW SLOT SEAL CHROME TRIM X X NN	1	\$	446.00	
90	FRONT NO PLATE / MC	S/N	\$	60.00	60
91	SUNDRIES ? ✓ NEC		\$	500.00	8.48
TOTAL SPARE PARTS			:	\$	37,603.00
TOTAL LABOUR CHARGES			:	\$	17,024.00
GRAND TOTAL			:	\$	54,627.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :

Steve (LKK)
 3/8/22, 2.00p

ON-11 12
 EXHIBIT - ?
 P/P
 4 BL. 9
 9 45

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT