

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh Zan Wei

Date: 10 Aug 2022

Preliminary Advice

Vehicle No	: SLV9454G	Accident Date	: 22/07/2022
Make	: NISSAN NOTE	Policy No.	: MP319712
Assignment Date	: 03/08/2022	Excess	: S\$500.00
Date of Inspection	: 08/08/2022	Est. Duration of Repair	: 5 DAYS
Inspection At	: AH LIM MOTOR COMPANY		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,794.20
Revised Amount	:S\$	4,076.10
Check Items (Estimated)	:S\$	1,023.00
Total	:S\$	5,099.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	29,648.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,352.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part Repair.
- Please note that the preliminary advice amount (Revised & Check) stated are subject to consistency check, part prices and labour cost.