

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN		Ref:	CS/CTI22007440/Eqy3		
	3 ANSON ROAD # SPRINGLEAF TOV		Date:	04/08/2022		
				Code:	СТІ	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GX 1392C	Veh. Inspected		FBG 7417A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM22D205323/C02/GX1392C/ THAMYL	Excess (\$)		0.00	
	Assign From	PAULINE THAM	Assign Date		04/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	. General Information					
	Accident Date Inspection Date					
	Survey held at	RACE WERKS MOTOR SPORTS				
		BLK 1008 BUKIT MERAH LANE 3 #01-26 SINGAPORE 159722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					