COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA2796Z Make : HYUNDAI Model : I-40 Date: 02.08.2022 Insurance: NTUC MVA: MS. LOKE YY

Qty Parts Description / Labour	Туре	Unit Price	Amount		
FRT DOOR MIRROR LH / P.3			s	670.00	
SUB TOTAL			s	670.00	
DISCOUNTED TOTAL			\$	536.00	
					Nett
			\$	-	Nett
abour Charge				200.00	l ss 150
			\$	150.00	\$0 100
CHECK WIRING AND LIGHTING			\$	30.00	X M
TOTAL LABOUR			\$	380.00	-
ESTIMATE TOTAL			\$	916.00	
1	SUB TOTAL LESS 20% DISCOUNTED TOTAL abour Charge ANEL BEATING PRAY PAINTING CHARGE HECK WIRING AND LIGHTING TOTAL LABOUR	SUB TOTAL LESS 20% DISCOUNTED TOTAL abour Charge ANEL BEATING PRAY PAINTING CHARGE HECK WIRING AND LIGHTING TOTAL LABOUR	SUB TOTAL LESS 20% DISCOUNTED TOTAL abour Charge ANEL BEATING PRAY PAINTING CHARGE HECK WIRING AND LIGHTING TOTAL LABOUR	\$ SUB TOTAL LESS 20% DISCOUNTED TOTAL \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	\$ 670.00 \$ 134.00 \$ 536.00 S 200.00 S 200.00 PRAY PAINTING CHARGE HECK WIRING AND LIGHTING TOTAL LABOUR \$ 670.00 \$ 134.00 \$ 30.00 \$ 380.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Paris prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

. No filegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Day
L/S
L/S
Lefter ryni photos
Grap
02/8/22 43epm