

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
 Defu Industrial Park C, Singapore 539186
 Tel : 6343-0934 Fax : 6343-0921
 Email : jmartauto@gmail.com
 Registration No: 201400246D
 GST Reg. No: 201400246D

TP ALG.

Xiao Tony

1-Aug-22

LRW 3F 7FA 0MC 38 4416

Our ref : TP/5147/22

Tan Choon Chieh

RE : estimate cost for vehicle no : SMZ 1798J

1 pc	frt bumper	<i>Defud</i>	\$	2,300.00	<i>✓ 893</i>	
1 pc	frt bumper lh retainer	<i>new</i>		140.00	<i>+</i>	
1 pc	frt bumper lower garnish	<i>cut</i>		320.00	<i>✓</i>	
1 pc	frt lh rim	<i>cut</i>		1,670.00	<i>✓ 1078</i>	
1 pc	rh taillamp	<i>cracked</i>		880.00	<i>✓ 380</i>	
1 pc	rear bumper	<i>Defud</i>		2,300.00	<i>✓ 783</i>	
1 pc	rear bumper rh retainer	<i>new</i>		180.00	<i>✓</i>	
3 pcs	rear bumper reverse sensor	<i>Repd 2 pieces</i>		840.00	<i>✓ 560</i>	
1 pc	rear rh fender	<i>cracked</i>		2,860.00	<i>✓ 1565</i>	<i>7846</i>
1 pc	rh body light	<i>cut</i>		380.00	<i>✓</i>	
1 pc	rear bumper rh reflector	<i>cut</i>		180.00	<i>✓</i>	
1 pc	rear bumper lower lip	<i>cut</i>		480.00	<i>✓</i>	<i>7061.40</i>
10 pc	rear bumper clips	<i>new</i>		60.00	<i>✓</i>	
1 pc	rear bumper sponge	<i>new</i>		260.00	<i>✓</i>	
1 pc	rear bumper reinforcement	<i>new</i>		1,010.00	<i>✓</i>	
1 pc	rear rh rim	<i>cut</i>		1,680.00	<i>✓ 1078</i>	
1 pc	rear rh tailgate reflector	<i>new</i>		780.00	<i>✓</i>	
1 pc	rear rh fender air guard	<i>new</i>		110.00	<i>✓</i>	
				16,430.00		
			less 10%	1,643.00		
				14,787.00		
1 pc	rear rh quarter glass gum	<i>new</i>		50.00	<i>snett</i>	
	Panel beating.			1,500.00	<i>1000</i>	
	Spray painting.			1,500.00	<i>1100</i>	
	Wiring.			30.00	<i>✓</i>	
	Rust proofing.			80.00	<i>✓</i>	
	Alignment.			80.00	<i>✓</i>	
				18,027.00		
				1,261.89		
				19,288.89		

2340

Admin Lj
 L/S 02/08/22
 08 Png

LKK Auto Consultants hence notify Plus 7% GST
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SD : Nineteen thousand two hundred eighty-eight & cents eighty-nine only.

7.5K

total: 9401.40
 L/S: 7.5K