

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM22D205103/C01/IRENE Date: 05<sup>th</sup> Oct 2022

Our Ref : CS/CTI22007470/Eqy3e2

## M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKJ 6456X ACCIDENT ON 21/07/2022

Instruction was received to inspect the vehicle Reg. No. SKJ 6456X. The inspection was conducted on 05/08/2022 at the premises of M/s Wearnes Automotive Pte Ltd, 45 Leng Kee Road, Singapore 159103.

The following vehicle information was recorded:

Registration Number : SKJ 6456X

Make/Model : Jaguar XF 2.0L GTDI

Year of Registration : 2013 Body Colour : Green

Chassis Number : SAJAC05N7DPS79817

Engine Capacity : 1999 cc Speedometer Reading : Not Available

The vehicle sustained damages at the rear portion. The Estimated repair cost of such vehicle is \$\$55,691.40 (Sin Dollars: Fifty-Five Thousand Six Hundred Ninety-One and Forty cents only.) (Exclude check items \$\$8,806.30Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 42,000.00 (est)

Less: LTA Reimbursement Value (RV) 36,046.00) S\$

> 5,954.00 **S**\$

Less: Excess 750.00) (S\$

Nett Liability 5,204.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 55,691.40

(Exclude check items S\$8,806.30Nett)

Less:Excess (S\$ 750.00)

Nett Liability

54,941.40

(a) - (b) =49,737.40)

The amount of estimated saving of S\$49,737.40 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

CHEN TSUE YEE

Automotive Assessor

MSc(Eng M), B Eng(Hons), PEng(UK), MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.