

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 08 Aug 2022

Preliminary Advice

Vehicle No	: SKJ6456X	Accident Date	: 21/07/2022
Make	: JAGUAR XF	Policy No.	: DMPCSNA00092412208
Assignment Date	: 08/08/2022	Excess	: S\$750.00
Date of Inspection	: 05/08/2022	Est. Duration of Repair	: 13
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (HQ) 45 LENG KEE ROAD SINGAPORE 159103		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	77,909.30
Revised Amount	:S\$	55,691.40
Check Items (Estimated)	:S\$	8,806.30
Total	:S\$	66,497.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	36,046.00
Salvage Value	:S\$	5,954.00
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (x) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.