



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22007479/Kcy3e2 Date: 17/02/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJR 6732T	Veh. Inspected	SMU 3944S
Policy No.	P10661141R00	Coverage (\$)	0.00
Claim No.	C10016078/CH	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	05/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTDKB3FUX03091114	Colour	METALLIC SILVER
Odometer	168173 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	9 mm
L/H Front Tyre	195/65 R15	SAILUN	9 mm
R/H Rear Tyre	195/65 R15	WANLI	8 mm
L/H Rear Tyre	195/65 R15	WANLI	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	25/06/2022	Inspection Date	05/08/2022
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	