

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 1/2

Document no.  
Document date 05-08-2022  
Customer no. 5211042669  
Customer GST-ID T11FC0131K  
Dealer 30001  
Job order number 2022020743/ 1  
Job order date 18-07-2022  
Service Advisor SHU SHI TANG

Company  
ALLIANZ GLOBAL  
CORPORATE & SPECIALTY SE  
SINGAPORE  
12 MARINA VIEW  
#14-01 ASIA SQUARE TOWER 2  
Singapore 018961

Customer Details:  
Ms.  
NG  
SOO YEE  
32 GREENLEAF VIEW  
SINGAPORE 279271

| License plate | Model code | First registration | VIN               | Model                               | Mileage |
|---------------|------------|--------------------|-------------------|-------------------------------------|---------|
| SKA1515P      | 5C83EZB0   | 28-02-2020         | VWVZZZ16ZKM505720 | Beetle Cabriolet 1.2 I TSI 77kW DSG | 23,257  |

| Position no.   | Description                              | Quantity | Unit | Unit price<br>excl. GST | Tax code | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------------|------------------------------------------|----------|------|-------------------------|----------|---------------------------|---------------------------|
| 9801B004       | B&P CHECK SHORT CIRCUIT / HARNESS REPAIR |          |      |                         | #1       | 200.00                    | 214.00                    |
| 9801B005       | B&P DIAGNOSIS AND PROGRAMMING            |          |      |                         | #1       | 360.00                    | 385.20                    |
| 9801B001       | TO ALIGN LED HEADLIGHT                   |          |      |                         | #1       | 100.00                    | 107.00                    |
| 5C5807217BHGRU | Cover For Bumper Primed                  | 1        | pcs. | 1,523.08                | 28.00%   | 1,096.62                  | 1,173.38                  |
| 5C5807109D     | Bumper Bracket                           | 1        | pcs. | 770.01                  | 28.00%   | 554.41                    | 593.22                    |
|                | REINFORCEMENT                            |          |      |                         |          |                           |                           |
| 5C5807651      | Cross Member                             | 1        | pcs. | 204.88                  | 28.00%   | 147.51                    | 157.84                    |
| 5C5807248F     | Foam Insert                              | 1        | pcs. | 160.02                  | 28.00%   | 115.21                    | 123.27                    |
|                | REINFORCEMENT FOAM ( SIDE )              |          |      |                         |          |                           |                           |
| 5C5807665B     | Foam Insert                              | 1        | pcs. | 34.55                   | 28.00%   | 24.88                     | 26.62                     |
|                | REINFORCEMENT FOAM ( UPPER )             |          |      |                         |          |                           |                           |
| 5C5807773E     | Holder For Cover Bumper                  | 1        | pcs. | 53.98                   | 28.00%   | 38.87                     | 41.59                     |
|                | BUMPER UPPER HOLDER LH                   |          |      |                         |          |                           |                           |
| 5C5807774E     | Holder For Cover Bumper                  | 1        | pcs. | 53.98                   | 28.00%   | 38.87                     | 41.59                     |
|                | BUMPER UPPER HOLDER RH                   |          |      |                         |          |                           |                           |
| 5C5807183A     | Guide Piece                              | 1        | pcs. | 43.29                   | 28.00%   | 31.17                     | 33.35                     |
|                | BUMPER SIDE BRACKET LH                   |          |      |                         |          |                           |                           |
| 5C5807184A     | Guide Piece                              | 1        | pcs. | 43.29                   | 28.00%   | 31.17                     | 33.35                     |
|                | BUMPER SIDE BRACKET RH                   |          |      |                         |          |                           |                           |
| N 90536901     | Rivet                                    | 4        | pcs. | 0.85                    | 28.00%   | 2.45                      | 2.62                      |
| 5C5853671T ZLL | Grille Satin Black/Bright                | 1        | pcs. | 358.10                  | 28.00%   | 257.83                    | 275.88                    |
|                | BUMPER CTR LOWER GRILLE                  |          |      |                         |          |                           |                           |
| 5C5854661K ZLL | Grille Black/Satin Black/                | 1        | pcs. | 208.77                  | 28.00%   | 150.31                    | 160.83                    |
|                | LHS FOG LAMP GRILLE                      |          |      |                         |          |                           |                           |
| 3C0973737      | Flat Contact Housing With                | 2        | pcs. | 21.54                   | 28.00%   | 31.02                     | 33.19                     |
|                | H/LAMP WIRE HOUSING                      |          |      |                         |          |                           |                           |
|                | LABOUR                                   | 3        | pcs. | 560.00                  | #1       | 1,680.00                  | 1,797.60                  |
|                | SPRAY PAINT                              | 3        | pcs. | 530.00                  | #1       | 1,590.00                  | 1,701.30                  |
|                | FRT NUMBER PLATE                         | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | ALLIANZ OD/RECOVERY                      |          |      |                         |          |                           |                           |
|                | DOA: 16/07/2022                          |          |      |                         |          |                           |                           |
|                | EXCESS:                                  |          |      |                         |          |                           |                           |
|                | SURVEY BY:                               |          |      |                         |          |                           |                           |

Quotation valid till 25-07-2022

| Tax Code | Labour | Material | Material Discount | GST % | GST    | Total Discount | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------|--------|----------|-------------------|-------|--------|----------------|---------------------------|---------------------------|
| #1       | 660.00 | 5,870.32 | 980.11            | 7%    | 457.12 | 980.11         | 6,530.32                  | 6,987.44                  |
| Total    | 660.00 | 5,870.32 | 980.11            |       | 457.12 | 980.11         | 6,530.32                  | 6,987.44                  |

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



SKODA

Commercial  
Vehicles

## Quotation

Non binding - Preview

|                  |               |
|------------------|---------------|
| Page             | 2/2           |
| Document no.     |               |
| Document date    | 05-08-2022    |
| Customer no.     | 5211042669    |
| Customer GST-ID  | T11FC0131K    |
| Dealer           | 30001         |
| Job order number | 2022020743/ 1 |
| Job order date   | 18-07-2022    |
| Service Advisor  | SHU SHI TANG  |

|               |            |                    |                   |                                     |         |
|---------------|------------|--------------------|-------------------|-------------------------------------|---------|
| License plate | Model code | First registration | VIN               | Model                               | Mileage |
| SKA1515P      | 5C83EZB0   | 28-02-2020         | WVWZZZ16ZKM505720 | Beetle Cabriolet 1.2 I TSI 77kW DSG | 23,257  |

Customer

Service Advisor

-----VISIT OUR WEBSITE: [aftersales.vw.com.sg](https://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](https://volkswagen.com.sg) and [www.skoda.com.sg](https://www.skoda.com.sg) (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.