

SKU6885



MIRAGE MOTORWERKZ PTE LTD

Main Branch
 10 Kaki Bukit Road 2
 #01-28/29 First East Centre
 Singapore 417868
 ☎ +65 6635 7111 ☎ +65 6635 7112

East Coast Branch
 Shell Autoserv @ Siglap
 40 Upper East Coast Road
 Singapore 455212
 ☎ +65 6977 7117

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before repair & spray painting
- To display damaged parts for resurvey

• Parts repairer must confirm

• Noisy, is on "Without Prejudice" basis

• No dispute/communications allowed

• Any repairs must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ESTIMATED REPAIR CHECKLIST

TO :	VEHICLE REGISTRATION NO.: SKU6885H
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: AUDI / Q8
CLAIM TYPE : OD PARTY CLAIM	CHASSIS NUMBER: KNAD6811VK6277852
ACCIDENT DATE/TIME :	CONTACT PERSON :

PARTS	QTY	PER UNIT	PRICES
1 FRONT RH FENDER <i>Painted</i>	1	\$ 2,592.00	\$ 2,592.00
2 FRONT RH FENDER WHEEL ARC GARNISH	1	\$ 607.00	\$ 607.00
3 FRONT RH FENDER EMBLEM	1	\$ 133.00	\$ 133.00
4 FRONT RH FENDER LOWER COVER	1	\$ 104.00	\$ 104.00
5 FRONT RH FENDER INNER GARNISH	1	\$ 60.00	\$ 60.00
6 FRONT RH WHEEL RIM	1	\$ 3,020.00	\$ 3,020.00
7 FRONT RH LOWER ARM	2	\$ 876.00	\$ 876.00
8 FRONT RH CONTROL ARM	1	\$ 423.00	\$ 423.00
9 FRONT RH STAY ARM	1	\$ 420.00	\$ 420.00
10 FRONT RH UPPER ARM	1	\$ 749.00	\$ 749.00
11 FRONT RH WHEEL BEARING	1	\$ 781.00	\$ 781.00
12 FRONT RH WHEEL BEARING HOUSING	1	\$ 880.00	\$ 880.00
13 FRONT RH SHOCK ABSORBER	1	\$ 3,410.00	\$ 3,410.00
14 FRONT RH DOOR	1	\$ 5,273.00	\$ 5,273.00
15 FRONT RH DOOR LOCK	1	\$ 395.00	\$ 395.00
16 FRONT RH DOOR WEATHERSTRIPE	1	\$ 191.00	\$ 191.00
17 FRONT RH DOOR LOWER COVER	1	\$ 535.00	\$ 535.00
18 FRONT RH DOOR LOWER COVER CHROME MOULDING	1	\$ 234.00	\$ 234.00
19 FRONT RH DOOR OUTER HANDLE HOUSING	1	\$ 98.00	\$ 98.00
20 FRONT RH DOOR OUTER CHROME MOULDING	1	\$ 305.00	\$ 305.00
21 FRONT RH DOOR INNER TRIM BOARD	1	\$ 4,241.00	\$ 4,241.00
22 FRONT RH DOOR GLASS POWER LIFTER	1	\$ 402.00	\$ 402.00
23 FRONT RH DOOR HINGE	2	\$ 121.00	\$ 242.00
24 FRONT RH DOOR CATCH	1	\$ 137.00	\$ 137.00
25 FRONT RH DOOR A PILLAR	1	\$ 4,980.00	\$ 4,980.00
26 FRONT RH DOOR ENTRANCE TRIM	1	\$ 872.00	\$ 872.00
27 DOOR FRAME CHROME MOULDING RH	1	\$ 598.00	\$ 598.00
28 FRONT RH WING MIRROR MOUNTING	1	\$ 2,132.00	\$ 2,132.00
29 FRONT RH WING MIRROR CAMERA	1	\$ 1,045.00	\$ 1,045.00
30 FRONT RH WING MIRROR GLASS	1	\$ 1,152.00	\$ 1,152.00
31 SILL PANEL WEATHERSTRIPE RH	1	\$ 282.00	\$ 282.00
32 REAR RH LOWER ARM	1	\$ 849.00	\$ 849.00
33 REAR RH UPPER ARM	1	\$ 748.00	\$ 748.00
34 REAR RH STRUT ARM	1	\$ 426.00	\$ 426.00
35 REAR RH STAY ARM	1	\$ 664.00	\$ 664.00
36 REAR RH CONTROL ARM	1	\$ 254.00	\$ 254.00
37 REAR RH WHEEL BEARING	1	\$ 862.00	\$ 862.00
38 REAR RH WHEEL BEARING HOUSING	1	\$ 847.00	\$ 847.00
39 REAR RH SHOCK ABSORBER	1	\$ 2,008.00	\$ 2,008.00
40 REAR RH WHEEL RIM	1	\$ 3,020.00	\$ 3,020.00
Sub total		SUBTOTAL :	\$ 43,515.00
Less 5%		LESS 5% :	\$ 2,175.75
Total List		PARTS TOTAL :	\$ 41,339.25

SPECIAL NBT	QTY	PER UNIT	PRICES
1 FRONT RH TYRE <i>tern</i>	1	\$ 580.00	\$ 580.00
2 FRONT RH DOOR INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
3 REAR RH TYRE <i>at</i>	1	\$ 580.00	\$ 580.00
Sub total		S/N TOTAL :	\$ 1,210.00

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 1,600.00	800
2 SPRAY PAINTING	\$ 1,200.00	700
3 WIRING	\$ 100.00	50
4 TO SPRAY TUFF COAT	\$ 200.00	60
5 TO TRANSFER DOOR FITTINGS	\$ 200.00	100
6 TO DISMANTLE FRONT UNDERCARRIAGE	\$ 350.00	200
7 FRONT DISMANTLE REAR UNDERCARRIAGE	\$ 350.00	200
8 TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80
9 TO PERFORM DIAGNOSTIC TEST	\$ 200.00	150
LABOR TOTAL :	\$ 4,350.00	

GRAND TOTAL 46899.25

2340

total 25342.45

r/s: 20.2K

07 Days