

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2022)**Parts:** 143 MERCEDES-BENZ GLC250D 2.1 4MATIC (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Success United Pte Ltd/SLT7798M/12/08/2022 12:05**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET INSULATOR <i>changed.</i>	0.00	0.00	✓ *190.00 F
2	1		*FRT FENDER GUARD LH <i>changed.</i>	0.00	0.00	✓ *155.00 F
3	1		*BONNET LINE FASTENER <i>changed.</i>	0.00	0.00	✓ *15.00 F
Sub Total (S\$)						360.00
+ Margin on L,N Items 10.00% (S\$)						36.00
Total Parts (S\$)						396.00

F=Franchise part.

Success United Pte Ltd/SLT7798M/12/08/2022 12:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Adm Lj
12/08/22
Resigned H.S.