



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22007523/Avce2 Date: 08/11/2022 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJW 40U	Veh. Inspected	SJL 8048D
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001227	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	08/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305084814	Colour	SILVER
Odometer	73062 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/55 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/55 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/55 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/08/2022	Inspection Date	08/08/2022
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	