

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SJL8048D
 ident Date : 7/8/2022
 Location : LOR CHUAN TOWARDS BOUNDARY ROAD

Model: TOYOTA ALTIS
 12/12/2008 - 11/12/2023
 3P: SJW40U (GREAT AMERICAN)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front under cover <i>3AP</i>	159.10	<i>x</i>	
2	10 pcs	Front under cover clips <i>3AP</i>		40.00	<i>x</i>
3	1 pc	Front air cleaner box <i>checked</i>	540.20	<i>477</i>	
4	1 pc	Front radiator fan assembly <i>checked</i>	670.20	<i>235</i>	
5	1 pc	Front n/s rim <i>3AP</i>		600.00	<i>x</i>
6	1 pc	Front n/s tyre <i>3AP</i>		150.00	<i>x</i>
Sub Total:			1,369.50	790.00	0.00
			25%	0%	10%
After Less %:			1,027.13	790.00	0.00
Total:			1,817.13		
After Less 20%:			1,453.70		

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)

712
 Supplementary: 534



☎ 8778 1999
 24 hr accident call

